LEGEND □ CABLE JUNCTION BOX CATCH BASIN CLEAN OUT 호 CONTROL VALVE LEGAL DESCRIPTION ☑ ELECTRIC SERVICE LOT 14 IN BLOCK 60, OCEAN BEACH ADDITION NO.3, ACCORDING -6- FIRE HYDRANT TO THE PLAT THEREOF RECORDED IN PLAT BOOK 2 AT PAGE 81, FP&L PAD OF THE PUBLIC RECORDS OF DADE COUNTY, FLORIDA. 9TH STREET CERTIFIED TO: 50' RIGHT-OF-WAY MANHOLE ASPHALT PAVEMENT MERIDIAN MANOR CONDO POOL EQUIPMENT CUT CURB-O POWER/LIGHT POLE PROPERTY ADDRESS **→** SPRINKLER SYSTEM 851 MERIDIAN AVENUE WATER METER ASPHALT PAVEMENT M M MIAMI BEACH, FL 33139 WATER VALVE M CURB 2' CURB & GUTTER ☑ WELL **BOUNDARY SURVEY** N.89'55'22"E. 140.00 - BW,0.2'S BRICK PAVERS 35.0 INVOICE # 41931 .21' 33' CENTERLINE SURVEY DATE 06/28/19 BW,2.0'W,0.1'N CONCRETE/CHAT 110.1 50.009 CONCRETE WALL FLOOD ZONE AE-8 (PLATTED AS PINE AVENUE)

MERIDIAN AVENUE 0.00 ELEVATION 50. MAP DATE 09/11/09 METAL FENCE ф MAP NUMBER 120651 0319L OVERHEAD WIRES WOOD DECK/DOCK 00,, WOOD FENCE LOT 14, BLOCK 60 CURB 5 STORY BUILDING **ABBREVIATIONS** BUILDING CORNER BACK OF WALK CALCULATED MEASURED FP&L-MANHOLE 00.00 39.9' NOT TO SCALE
OPEN PORCH
OFFICIAL RECORDS BOOK
POINT OF CURVATURE
POINT OF BEGINNING
POINT OF REVERSE CURVE
PERMANENT REFERENCE MONUMENT
POINT OF TANGENCY
END OF FENCE
EDGE OF PAVEMENT
EDGE OF WATER
FENCE LINE
FOUND IRON PIPE
FOUND IRON PIPE
FOUND IRON PIPE
FOUND IRON PIPE
FOUND NAIL
FOUND NAIL
FOUND NAIL
FOUND NAIL
SET NAIL & DISC
FLORIDA
SET NAIL & DISC
SCREENED PORCH
SET 1/2" PIN & CAP # 5495 NOT TO SCALE . 00 METAL UTILITY LID 6.7 35.0' S.89'55'22"W. 140.00 CORNER, 0.2'N-CORNER, 0.1'N BW,2.0'S,1.7'S (ASSUMED) LOT 13, BLOCK 60 R RAD SN&D SP SP&C ATLANTIC OAST 1. BASIS OF BEARINGS AS INDICATED ON SKETCH. 2. LEGAL DESCRIPTION PROVIDED BY CLIENT. 3. THE LANDS SHOWN HEREON WERE NOT ABSTRACTED BY THIS OFFICE FOR EASEMENTS, RIGHT-OF-WAYS, OWNERSHIP OR OTHER INSTRUMENTS OF RECORD. 4. UNDERGROUND OR INTERIOR PORTIONS OF FOOTINGS, FOUNDATIONS, WALLS OR OTHER NON-VISIBLE IMPROVEMENTS WERE NOT LOCATED.
5. ELEVATIONS ARE BASED ON THE NORTH AMERICAN VERTICAL DATUM OF 1988 UNLESS OTHERWISE 6. FENCE TIES ARE TO THE CENTER-LINE OF FENCE. WALL TIES ARE TO THE FACE OF WALL 7. IN SOME INSTANCES GRAPHIC REPRESENTATIONS HAVE BEEN EXAGGERATED TO MORE CLEARLY ILLUSTRATE THE CONTROL THE LOCATION OF THE IMPROVEMENTS OVER SCALED POSITIONS. 8. THE DIMENSIONS AND DIRECTIONS SHOWN HEREON ARE IN SUBSTANTIAL AGREEMENT WITH RECORD VALUES UNLESS OTHERWISE NOTED. PAUL J STOWELL PROFESSIONAL LAND SURVEYOR 9. PARTY WALLS ARE CENTERED ON PROPERTY LINE AND ARE 0.7' WIDE UNLESS OTHERWISE NOTED. 10. EXISTING CORNERS FOUND OFF WITNESS PROPERTY CORNERS Scale 1" FLORIDA CERTIFICATION NO. 5241 20' ATLANTIC COAST SURVEYING, INC. 11. OBSTRUCTED CORNERS ARE WITNESSED BY IMPROVEMENTS. 6129 STIRLING RD SUITE 2 DAVIE, FLORIDA 33314 12. NO ATTEMPT WAS MADE TO LOCATE WRITTEN OR UNWRITTEN EASEMENTS OR RIGHTS-OF-WAY, OTHER OFFICE: 954.587.2100 FAX:.954.587.5418 THEN THOSE SHOWN HEREON.