A "0" in the DBH column denotes no trunk at 4.5 feet above grade

H/Ct is approximate overall height of trees and approximate overall height of clear trunk of palms

For multi-trunked palms overall height of clear trunk is the approximate measurement of the tallest trunk

Canopy diameter is approximate and measured in one direction

4350 Nautilus Drive Miami Beach, Florida 33140-2824

LEGAL DESCRIPTION

Lot 7, Block 18, NAUTILUS EXTENSION SECOND, according to the Plat thereof, as recorded in Plat Book 34, Page 81, of the Public Records of Miami-Dade

FOLIO NUMBER: 02 3222 007 0070 (Miami-Dade County Public Records/Property Appraiser's Office)

SURVEYOR'S NOTES:

All distances as shown hereon are based on the US Survey foot.

At the time of Survey, The National Flood Insurance Rate Map for Florida, Community Panel No. 120651 (City of Miami Beach) 12086 C, 0309 L, FIRM Date 09/11/2009 and Revised with an effective date of 09/11/2009, published by the United States Department of Housing and Urban Development, delineates the herein described land to be situated within the Special Flood Hazard Area designated by the Federal Emergency Management Agency (FEMA). Subject property lies within Flood Hazard Zone "AE", Base Flood Elevation 7 feet. The Base Flood Elevation "AE" 7' refers to the NGVD (1929) Datum.

All elevations as shown on this survey drawing are referred to the National Geodetic Vertical Datum, 1929 (NGVD).

BENCHMARK REFERENCES:

Dade County BM D-157-R - ADJUSTED BM Name: D-157-R BM Elevation (NGVD 1929): 4.93 feet Location 1: 44 ST --- 35' SOUTH OF C/L Location 2: ALTON RD --- ON C/L

Description 1: PK AND BRASS WASHER IN CONC BULLNOSE OF INTERSECTION.

Dade County BM D-106 - ADJUSTED BM Name: D-106 BM Elevation (NGVD 1929): 3.20 feet Location 1: 43 ST --- 125' SOUTH OF PROJECTED SOUTH EDGE OF PAVEMENT Location 2: ALTON RD --- 15' WEST OF WEST EDGE OF PAVEMENT Location 3:30' SOUTH OF A SIGN READING "I-195 W & ALTON RD S" Description 1: PK NAIL AND BRASS WASHER IN NE CORNER OF A STORM DRAIN.

The floor elevations as shown on this survey drawing were taken from the outside of the house only. No access was available to the surveyor to the inside of the house at the time of survey. There may be different levels of elevation inside the house not known to the surveyor.

Some elevations as shown hereon were obtained by using RTK - GPS measurements and are subject to variations due equipment vertical displacement.

Survey done by occupation, physical evidence, the recovery of existing property corners, field measurements, calculations, adjacent plats and legal description provided to the surveyor and also from the Miami-Dade County Public Records/Property Appraiser Office and no claims as to ownership are made or implied.

Distances from property lines to fences or walls may slightly varies due to their irregularity, width and composition. Fences or walls not always travel on a straight line and in most cases meander through trees, hedges, vines and heavy landscaping usually located along boundary lines, therefore the resultant of said dimensions as shown hereon may vary slightly within 0.30' to 0.50' of a foot more or less.

The legal ownership of the fences and/or walls as shown hereon was not determined, and the locations as shown are based on the recovered boundary monumentation and calculations

Adjacent properties were not investigated at the time of this Survey.

Any fencing, walls, entrance features and landscaping could be subject to a "Safe Sight Distance Triangle" rule

Call 811 or visit www.sunshine811.com before digging.

No all property corners were not recovered at the time of the updated survey work.

The location of the trees as shown on this survey drawing are compiled from such field surveys deemed necessary by Jorge L. Cabrera, PSM, therefore the resultant of said dimensions shown hereon could vary slightly within 1 to 2 feet more or less. The subject property has heavily overgrown vegetation, shrubs and vines along all boundary lines. Shrubs and vines were not located.

The Tree Table as shown hereon was prepared by certified Arborist Jeff Schimonski, information below:

President, Tropical Designs of Florida, Inc. Member, American Society of Consulting Arborists ISA Certified Arborist Municipal Specialist FL-1052AM ISA Tree Risk Assessment Qualification LIAF Florida Certified Landscape Inspector - 2016-0175 305-773-9406 Jeff@TropicalArboriculture.com www.TropicalDesigns.com www.MalaysiaFlora.com

**CERTIFIED TO:** 

4350 Nautilus LLC

**GENERAL SURVEYOR'S NOTES:** 

- 1)-This survey was conducted for the purpose of a "Boundary Survey" only and is not intended to delineate the regulatory jurisdiction of any federal, state, regional or local agency, board, commission or other entity.
- 2)- The accuracy obtained by measurements and calculations on this survey, meets and exceeds the Minimum Technical Standards requirements for a suburban area (1 foot in 7,500 feet) as specified in Chapter 5J-17, Florida Administrative Code.
- 3)-This Survey does not reflect or determine ownership. 4)-Legal Description subject to any dedications, limitations, retractions reservations or easements of record.
- 5)-Examination of the Abstract of Title will have to be made to determine recorded instruments, if any affecting the property; search of Public Records not performed by this office
- 6)-No effort was made by this office to locate any underground utilities and/or structures within or abutting the subject property. 7)-This Survey has been prepared for the exclusive use the entities named hereon only and certifications hereon do not extend to any unnamed parties.
- 8)-This Survey was prepared for a Mortgage Transaction only; not to be used for design and/or construction purposes without the consent of this office.
- 9)-Utility facilities within Utility Easements not noted as violations.
- 10)-Driveways or portions thereof within Roadways not noted as violations or encroachments. 11)-Foundations and/or footings underneath the ground surface that may cross beyond the boundary lines of the herein described parcel are not shown.
- 12)-Fence ownership determines by visual means only (if any); Legal ownership not determined. 13)-No search records was made by this firm beside the record plat; therefore we do not imply or accept responsibility for any Easement, Dedication or
- Limitation for which information was not furnished.
- 14)-Contact the appropriate authorities prior to any design work on the hereon-described parcel for Building and Zoning information. 15)-In some instances graphic representations have been exaggerated to more clearly illustrate the relationship between physical improvements and/or
- lot lines. In all cases dimensions shall control the location of the improvements over scaled positions. 16)-The dimensions and directions shown hereon are in substantial agreement with record and calculated values unless otherwise noted.
- 17)- Obstructed corners are witnessed by improvements

This is to certify to the above named firm and or persons that the "SKETCH OF BOUNDARY SURVEY" of the herein described property is true and correct to the best of my knowledge and belief as recently surveyed under my direction, also there are no visible encroachments other than those shown. Owner or his representative furnished the legal description contained herein. Other recorded instruments may affect this property. Surveyor has not examined the abstract of title. Locations of utilities on or adjacent to the property were not secured unless specifically requested by owner. I further certify the Attest of plat meets the Standards of Practice and the Minimum Technical Standard Requirements, adopted by the Board of Professional September 2015 pursuant to Chapter 472.027 Florida Statutes, as set forth in Chapter 5J-17, Florida Administrative Code, under Sections 5J-17, P1 end 59-17/152 20 "BOUNDARY SURVEY" as defined in Section 5.I-17 050

LAST REVISION 06/29/2022 JN 22-6550-A

NOT TO SCALE

JORGE L. CABRERA

Professional Surveyor & Mapper, # 6487

CABRER/veyor and Mapper

CHECKED BY: JLC. DRAWN BY: JF / ELF FIELD DATE: 01/10/2022 01/11/2022 SCALE: 1" = 20' JOB No. 22-6550

OF 1

This drawing is the property of Jorge L. Cabrera Professional Surveyor & Mapper Reproductions of this drawing are not valid unless Signed and embossed with the surveyor's sea