

Exhibit A



Building Services Report

January 25, 2023








AFTER








BEFORE
(Change 2 Lights)































BEFORE



AFTER






BEFORE



AFTER



BEFORE



AFTER



BEFORE






AFTER



BEFORE



AFTER





BEFORE




AFTER




BEFORE




AFTER




BEFORE



AFTER







BEFORE



AFTER



BEFORE










After











Led light side walk 2
level completed

