
& The Gilded Lily Café


 1766 Bay Road - Mirmi Berch, Florida, 33139

### Existing Floor Plan For: Blue Dahlia Cantina & Privado Lounge Restaurant

DJU «Group, LIC et donco). Instruction & Restaurant, Concepts Nicole Bowwel (Ilewsole Bicoli 305.510.2.002

GROUND FLOOR PLAN





### KEY DIRECTIONAL PLAN

1766 Bay Road Final Submittal 11 26 18

### Exterior:

- 1. Front of the building, located at the southeast corner at the intersection of 18th street and Bay Rd., corner to corner, taken from across the street.
- 2. Front of the building across the street.
- 3.East side of the building.
- 4. East side of the building taken across the street.
- 5. East side of the building taken across the street.
- 6. Sidewalk at East side of the building.
- 7. North side of the building and surrounding property.
- 8. North road and surrounding properties.
- 9. North surrounding properties taken across the street.
- 10. North surrounding properties taken from the building.
- 11. Property located across the street at the North side of the building.
- 12. Property located across the street at the Northeast of the building.
- 13. Property located across the street at the Northeast of the building.
- 14. Properties located across the street at the East side of the building.
- 15. Property located next to the building at the East side.

### Interior of Blue Dahlia Cantina:

- 1.Bar and Entrance
- 2. Dining area
- 3.Bar
- 4.Bar and East side
- 5. Dining area and Bar
- 6. Ceiling details of the Blue Dahlia Cantina interior


### Interior of Gilded Lily:

- 1. Serving area, picking up area and waiting area
- 2.Bakery, preparation and souvenir counter area

### Interior of Privado Lounge:

- 1.Lounge Bar
- 2.Dine in area and Bar
- 3. Dine in area taken from the entrance





### KEY DIRECTIONAL PLAN


- street and Bay Rd., corner to corner, taken Front of the building, located at the from across the street. southeast corner at the intersection of 18th
- ωΝ Front of the building across the street.
- East side of the building.
- 4 East side of the building taken across the
- 5 East side of the building taken across the
- 6 Sidewalk at East side of the building.
- 7 property. North side of the building and surrounding
- 9.  $\infty$ North road and surrounding properties.
- North surrounding properties taken across the street.
- 10. North surrounding properties taken from the
- Property located across the street at the North side of the building.
- 13. Property located across the street at the Northeast of the building. Property located across the street at the

12.


- 14. Properties located across the street at the Northeast of the building.
- 5 Property located next tho the building at the East side. East side of the building.




































## Bar and entrance

- Dining area
- Bar and east side
- Dining area and bar
- Ceiling details of the Blue Dahlia Cantina interior.







# Interior of The Gilded Lily Cafe:

- Serving area, picking up area and waiting area
- . Bakery display, preparation and souvenir counter area.





## Interior of Privado Lounge:

- Lounge Bar.
- Dine in area and bar.
- Dine in area taken from the entrance.