Ownerwas. A. P. Forcum Mailing Address ALTON BEACH REALTY CO. B.	mit No. 6438	
Lot 1 Block 67-B Subdivision ReSUB of Block	1. 1350 Street 15th Terra	eDate Nov. 1-1934
General Contractor Wm. Goodman	Address -	
Architect Robert M. Little. 0050	Address	
Front 38 Depth51 Height 23	Stories Use	2- Family RESIDENCE
Type of construction C/B/STUCCOCost \$9,500.00	Foundation con.pile	Roof Comp & Tile
Plumbing Contractor McCaughn permit 7731	Address	Date 11-28-34
No. fixtures 9 Gas 6; Rough approved by		Date
Plumbing Contractor	Address	Date
No. fixtures set Final approved by		Date
Sewer connection 1 Septic tank	Make	Date
Electrical Contractor Larkins- permit #4671	Address	Date 11-28-1934
No. outlets 26Heaters Stoves Motors 2  Receptacles 24  Rough approved by	Fans Temporary service Date	
Electrical Contractor Larkins permit 4796	Address	Date 12-26-34
No. fixtures set 28 Final approved by		Date
Date of service		
Alterations or repairs # 5371; Garage & 2 Maid's rooms W.F. Studwell, contractor: Geo. A. Coffin, arch	hitect c-b-s	DateJune 16-1936
Plumbing permit; #9127:- 4 fixtures McGui: Electrical Permit # 6806; Triangle Elec. Co. 8 out	re	- June 18-1936 July -8-1936
BUILDING PERMIT #35277 Remodeling 1st floor into on Rubinson, contr. Transf	e unit apartment-400 sq.ft. erred to A. KAPLAN,\$ 2,000 4,1951 OMP/q	or over-Norman
PLUMBING PERMIT: # 32439 Parker Plumbing Co: 1 Water c water heater: Oct.8, 1951 10 #32543 Parker Plumbing Co: 1 Gas re	closet, 1 Lavatory, 1 Shower 0-30-51 LR ange: 10-30-51 ok Rothman 1	*O1100 [[] h.h.h. [.H

Bond 1395 BUILDING PERS

#74956 Snapp Inc.: Sandblas erior - \$460 - 10/11/65

#82856 Pablo Aguilera Pai ing Cont. - clean & paint exterior only. Must comply with Ord. 1060 \$500.00 8721/69

14928-Guaranttee Ext.Co.-Fumigation-\$475-4-27=79
#31373 - 11-24-87 - Gwner - Galvanized chain link fence - \$25.00

ELECTRICAL PERMITS # 35227 Max Belin: 5 Switch outlets, 5 Receptacles, 4 Light outlets, 4 fixtures,

1 Refrigerator, 1 Iron, 1 Water heater, 1 Appliance, 2 Centers of distribution,

1 Service: October 12, 1951 BK - H. O.Rosser 10/31/51

1521 Bay Rd. #54212 Astor Elec: 1 motor 0-1 HP, 9/11/59 OK 9/17/59 Newhold #59810 C. J. Kay Elec. Co.: 3 motors, 0-1 hp; 1 cent. of dist.; 1 serv. equipment = 7/8/63 #82219 - Ocean Electric Co. - Repair meter - 7-28-87

### COASTAL CONTROL ZONE

### CUMULATIVE COST OF CONSTRUCTION OF PERMITS ISSUED

DATE	PROCESS	DESCRIPTION	WORK	CUMULATIVE	APPRAISED BLDG.		BUILDING
ISSUED		OF WORK	COST		VALUE BEFORE REMODEL	% COMMENTS	PERMIT NO
1-24-87		CHAIN LINK FENCE	25.00				3/373
		*					
							н.
-				*			

## COASTAL CONTROL ZONE CUMULATIVE COST OF CONSTRUCTION OF PERMITS ISSUED

					<del></del>			1
	PROCESS		WORK	CUMULATIVE	APPRAISED BLDG.		SECURIO MATERIAL DE CONTRACTOR	BUILDING
135UED 12-7-88	NO.	OF WORK	COST	WORK COST	VALUE BEFORE REMODEL	8	COMMENTS	PERMIT NO.
127.88		35 LIPT. WOODEN Fence	#300.00			\$50 EVE		s6886353
		fence						
				-				
					mar 4000m.			
						1		
		,		1 B 3 4				
			4500					
			4 1					
					v			
			19 10					
			40					
					20		*	
					· ·			
				7				
		All Man						
		A STATE OF THE STA						

BUILDING PERMITS: #SB880353 - Julie Rose - 35 L. Ft. wooden fence - \$300.00 - 12-7-88

nger DEMOLISHED Owner OTIS DANIEL	Mailing Address	Permit No. 6617	SHED
Lot 2 Block 67-B	Subdivision ALTON BEACH	No. 1344 Street 15th Terrac	eDateDec. 14-19
General Contractor owner	Resub-	Address	Total Control
Architect owner		Address	
Front 20 Depth 30	Height 15-4	Stories Use o	arage
Type of construction block	Cost \$500.00	Foundation	Roof
Plumbing Contractor Alex.		Address	Date Feb. 1-193
No. fixtures 3	Rough approved by		Date
Plumbing Contractor		Address	Date
No. fixtures set	Final approved by		Date
Sewer connection 1 (Orr)	Septic tank	Make	Date
Electrical Contractor		Address	Date
No. outlets Heaters	Stoves Motors	Fans Temporary service	
Rough approved by		Date	
Electrical Contractor		Address	Date
No. fixtures set	Final approved by		Date
Date of service			

#58261 Turkel & Son: Demolition of all buildings - \$500.00 - Jan. 12, 1959

**Šinger** 

BV07001023	BV07000573	BSL1600065	BS950497	BS920750	BR150024	BR040297	BP071951	BP071246	BM940825	BE970958	BCU1100487	B0605860	B0504768 B0602351	Permit #
STRUCT	ENGINEER	,	HTO	HTO	1600 de la constante de la con		ALTRMDL	ALTRMDL	ALI	ALT	PRIMARY	PAINT-R	RPR-R	Sub Type
CLOSED	CLOSED	OPEN	CLOSED	CLOSED	IN VIOL	CLOSED	FINAL	FINAL	CLOSED	FINAL	APPROVED	FINAL	FINAL	Status
17-May-07	08-Mar-07	07-Apr-16	22-Dec-94	14-Jan-92	06-Nov-14	15-Sep-04	21-Sep-07	10-May-07	28-Apr-94	01-Apr-97	07-Mar-11	09-Aug-06	10-Jun-05 24-Feb-06	APPLIED
17-May-07	08-Mar-07		22-Dec-94	14-Jan-92		04-Nov-04	21-Sep-07	10-May-07	28-Apr-94	01-Apr-97	11-Mar-11	09-Aug-06	01-Jul-05 27-Feb-06	APPROVED
30-Aug-11	06-Sep-07		20-Jun-95	12-Jul-92		04-Nov-14	23-Mar-08	07-Nov-07	02-Nov-94	12-Jan-98			28-Dec-05 06-Nov-06	EXPIRED
N.O.V. ISSUED FOR WATER LEAKS FROM BATHROOM CAUSING CEILING IN ROOM BELOW TO COLLAPSE. NEED TO MAKE ALL NECESSARY REPAIRS AND OBTAIN PERMITS FOR ALL TRADES INVOLVED SUCH AS PLUMBING AND BUILDING.	FAILURE TO COMPLY WITH THE REQUIRED RECERTIFICATION OF BUILDING 40 YEAR OLD - MIAMI DADE COUNTY CODE Ordinance Section 8-11(f).	MDC-USB INVOICE #US2016-006-B, DATED 03/25/2016, FOR HEARING HELD, ON MARCH 09, 2016, FOR PROPERTY LOCATED AT 1344 15TH TERRACE, MIAMI BEACH, FL.  AMT. DUE \$23.55  NOTICE OF VIOLATION ISSUED.  Violation BR150024 not in compliance, therefore, as per the Florida Building Code and Miami-Dade County chapter 8-5 (6) the property is deerned unsafe if a 40 Year Recertification report is not completed.  You must have the 40 Year Rec. processes completed within thirty calendar days from the posting of this notice.  Sec. 8-5 Unsafe Structures  Sec. 8-5 Unsafe Structures subject to the recertification requirements in Section 8-11(f) of this Code which the owner fails to timely respond to the Notice of Required Inspection or fails to make all required repairs or modifications found to be necessary resulting from the recertification inspection by the deadline specified in the Code or any written extension granted by the Building Official will be demolished		RPLC 27 JAL WDWS W/27 S/H WDWS-26 OPNNGS	RECERTIFICATION OF BUILDING 40 YEAR OLD - MIAMI DADE COUNTY CODE Ordinance Section 8-11(f).	Ten Years Building Re-Certification.	23-Mar-08 MISC REPAIRS TO CORRECT VIOLATION BV07001023/REPAIR WATER PIPE INCEILING.	To correct#BV07000573/ Correct flue& vent pipe	02-Nov-94 INST 18000BTU RAC	BURGLAR ALARM SYSTEMS		EXTERIOR PA	GUNITE REPAIR TO EXTERIOR TIE BEAMS AND COLUMNS.	DESCRIPTION
1344	1344	1344	1344	1344	1344	1344	1344	1344	1344	1344	1344	1344	1344	
15TH TE	15TH TE	15TH TE	15TH TE	15TH TE	15TH TE	15TH TE	15TH TE	15TH TE	15TH IE	15TH TE	15TH TE	15TH TE	15TH TE	DIRI STREET_NAME
32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	32330160090	

BV15000495 UNSAFE
UNSAFE
OPEN
13-Feb-15
13-Feb-15

15th

вую	вию	BSECLIEN	BSBUILD	BSBUILD	BREC	BREC	BPLUM	BPLUM	BMISC	BMECH	BELEC	ВСИ	<b>BSBUILD</b>	<b>BSBUILD</b>	<b>BSBUILD</b>	COMP
																TYPE

AMERICAN SOCIETY OF CIVIL ENGINEERS NATIONAL ACADEMY OF BUILDING INSPECTION ENGINEERS

NATIONAL SOCIETY OF PROFESSIONAL ENGINEERS FLORIDA ENGINEERING SOCIETY


9. N. Sheingold, P.S. P. CONSULTING ENGINEER PROFESSIONAL BUILDING INSPECTION 12420 S.W. 75th AVE., / MIAMI, FLORIDA 33156 TELEPHONE: (305) 378-1244 Established 1976


Page 2

- 7. Gunite to original dimension. Engineer's inspection required to verify removal of all loose debris and adequate coating of rebar.
- 8. Remove all construction debris from job site.

All work to be in accordance with ICRI 03730 and ACI 318-99.

In progress inspections will be performed and a final inspection report will be forwarded upon completion.







# CITY OF MIAMI BEACH BUILDING DEPARTMENT 1700 CONVENTION CENTER DRIVE 2ND FLOOR - CITY HALL MIAMI BEACH, FL 33139

## NOTICE TO THE CITY OF MIAMI BEACH BUILDING DEPARTMENT OF EMPLOYMENT AS SPECIAL INSPECTOR UNDER THE FLORIDA BUILDING CODE

I, (we) have been retained by: LINDS JELINEK to perform special inspector services under
the Florida Building Code at the 1344 15 the 1540
of 5.23.05 (date). I am a Professional Engineer or Architect licensed in the State of Florida.
Process Number: 3066231 Master Permit (IF APPLICABLE):
O Special Inspector for Pilings, FBC 1822.1.20
Special Inspector for Soll Compaction, FBC 1820.3.1
Special Inspector for Precast Attachments, FBC 1927.12.2 (By P.E. or R.A)
Special Inspector for Reinforced Masonry, FBC 2122.4
<ul> <li>Special Inspector for Reinforced Masonry, FBC 2122.4</li> <li>Special Inspection for Steel Bolted &amp; Welded Connections, FBC 2218.2 (By P.E. or R.A)</li> <li>Special Inspector for Trusses over 35 feet long or 6 feet high, FBC 2319.17.2.4.2 (By P.E. or R. A)</li> </ul>
O Special Inspector for Trusses over 35 feet long or 6 feet high, FBC 2319.17.2.4.2 (By P.E. or R. A)
Special Inspector for GUNITE REPOR.
NOTE: Only the marked boxes apply.
The following individual's employed by this firm or me are authorized representatives to perform inspections*
1. J.N. HEWGOLD P.E. 2.
3. /
*NOTE: FBC 2001 HVZ sections 1927.12.2, 2218.2, 2319.17.4.2 requires either a Registered
professional Engineer or Registered Architect to perform the actual inspections.
I, (we) will notify the City of Miami Beach Building Department of any changes regarding authorized personnel performing inspection services.
t, (we) will notify the City of Miami beach Building Department of any changes regarding authorized personnel performing inspection services.
I, (we) understand that a Special Inspection Log for each building must be displayed in a convenient location on the site for reference by the City
of Miami Beach Building Department Inspector. All mandatory inspections, as required of the Florida Building Code, inspection performed by the Special inspector blied by the Owner are in addition to the mandatory inspections performed by the Building Department. Further more, upon
completion of the work under each building permit, I will submit to the Building Inspector at the time of final inspection the completed Inspection
Log form and sealed statement that, to the best of my knowledge, belief and professional judgment those portions outlined above meet the intent of the Florida Building Code and are in subsequent accordance with the approved plans.
to the richal balloting code and are an subsequent accordance with the approved plans.
Architect/Engineer Signature:
Architect/Engineer Name Printed:
Address: 12420 SW 75 AVE PINCEST
1040 30 / 3000
Phone Number: 305. 378. 1244
Signed and Sealed Phone Number: 305.378.1244  Owner/Agent Signature: Signature:
Signed and Sealed

AMERICAN SOCIETY OF CIVIL ENGINEERS NATIONAL ACADEMY OF BUILDING INSPECTION

**ENGINEERS** 

J. N. Sheingold, P.E.

CONSULTING ENGINEER
PROFESSIONAL BUILDING INSPECTION
12420 S.W. 75th AVE., / MIAMI, FLORIDA 33156
TELEPHONE: (305) 378-1244
Established 1976

NATIONAL SOCIETY OF PROFESSIONAL ENGINEERS FLORIDA ENGINEERING SOCIETY

16 February, 2006

City of Miami Beach Building Department 1700 Convention Center Drive Miami Beach, Florida 33139

Att: Building Official

Dear Sir:

We have been retained by the owners of 1344 15<sup>th</sup> Terrace, Miami Beach, to provide special inspector services as defined in section 105 of the F.B.C. The repairs are to be performed by Robbins Gunite, under contract to the owner. The repairs will consist of the following:

- 1. Gunite repair to approximately 250 Lineal Feet of reinforced concrete tie beam.
- 2. Gunite repair to approximately 120 lineal feet of reinforced concrete tie column.

### Repair Procedure

- 1. Remove all loose and spalling concrete using a light chipping hammer. Note: no additional chipping without approval of Engineer.
- 2. Inspect exposed interior reinforcing steel and replace any steel damaged in excess of 10%. Should laps be required, at least 48 bar diameters or 30 inch minimum is required as per ACI 318-99. Steel is to be 60 KSI. Concrete cover for steel rebar is to be a minimum of 1.5 inches.
- 3. Should steel replacement be required, embedment of rebar into existing concrete structures is to be a minimum of 9 inches and Sika 31 Gel epoxy is to be used. No areas are to be concealed without Engineer's approval.
- 4. Provide shoring, where required, to support roof members above tie beam.
- 5. Install stirrups on all tie beams and columns. Spacing to be 10 inches on center.
- 6. Sandblast existing exposed rebar and coat with Armatec 110 or equivalent.

AM106

AMERICAN SOCIETY OF CIVIL ENGINEERS NATIONAL ACADEMY OF BUILDING INSPECTION ENGINEERS

NATIONAL SOCIETY OF PROFESSIONAL ENGINEERS FLORIDA ENGINEERING SOCIETY

9. N. Sheingold, P.E. P CONSULTING ENGINEER PROFESSIONAL BUILDING INSPECTION 12420 S.W. 75th AVE., / MIAMI, FLORIDA 33156 TELEPHONE: (305) 378-1244 Established 1976

Page 2

- 7. Gunite to original dimension. Engineer's inspection required to verify removal of all loose debris and adequate coating of rebar.
- 8. Remove all construction debris from job site.

All work to be in accordance with ICRI 03730 and ACI 318-99.

In progress inspections will be performed and a final inspection report will be forwarded upon completion.

AMERICAN SOCIETY
OF CIVIL ENGINEERS
NATIONAL ACADEMY
OF BUILDING INSPECTION

**ENGINEERS** 

J. N. Sheingold, P.E.

CONSULTING ENGINEER
PROFESSIONAL BUILDING INSPECTION
12420 S.W. 75th AVE., / MIAMI, FLORIDA 33156
TELEPHONE: (305) 378-1244
Established 1976

NATIONAL SOCIETY OF PROFESSIONAL ENGINEERS FLORIDA ENGINEERING SOCIETY

16 February, 2006

City of Miami Beach Building Department 1700 Convention Center Drive Miami Beach, Florida 33139

Att: Building Official

Dear Sir:

We have been retained by the owners of 1344 15<sup>th</sup> Terrace, Miami Beach, to provide special inspector services as defined in section 105 of the F.B.C. The repairs are to be performed by Robbins Gunite, under contract to the owner. The repairs will consist of the following:

- 1. Gunite repair to approximately 250 Lineal Feet of reinforced concrete tie beam.
- 2. Gunite repair to approximately 120 lineal feet of reinforced concrete tie column.

### Repair Procedure

- 1. Remove all loose and spalling concrete using a light chipping hammer. Note: no additional chipping without approval of Engineer.
- 2. Inspect exposed interior reinforcing steel and replace any steel damaged in excess of 10%. Should laps be required, at least 48 bar diameters or 30 inch minimum is required as per ACI 318-99. Steel is to be 60 KSI. Concrete cover for steel rebar is to be a minimum of 1.5 inches.
- 3. Should steel replacement be required, embedment of rebar into existing concrete structures is to be a minimum of 9 inches and Sika 31 Gel epoxy is to be used. No areas are to be concealed without Engineer's approval.
- 4. Provide shoring, where required, to support roof members above tie beam.
- 5. Install stirrups on all tie beams and columns. Spacing to be 10 inches on center.
- 6. Sandblast existing exposed rebar and coat with Armatec 110 or equivalent.

4	WEERS  WEERS  WEERS  WESTALL ENGANCED A  WESTALL AND COLOR  WESTALL AND COLOR  ENGANCED A  WOOFESTO  OF BUILDING SIGNEDTO  INCORPORATION  INCORPORATION	134+	Claud your	***	+
	AMERICAN SOCIETY OF CALL BUSINESS NATIONAL ACADEMY OF BULDING INSPECTION PROFESSIONAL BULDING INSPECTION 12420 S.W. TSM. AME. / MAINT RESTORATION TREFFICIEL FAUNT FORMS AND SOCIETY ESTATUME, CALLING INSPECTION TREFFICIEL FAUNT FORMS AND SOCIETY ESTATUME (1978) 71-244	1344  5 <sup>12</sup> -Tabpy 5.83.05	CASSON OF CASSON	Lettown Osman (ATI)	Jun 35
	CITY OF MIAMI SEACH SUILDING DEPARTMENT 1709 CONVENTION CHATER DRIVE 2ND FLOOR - CITY HAIL MIAMI SEACH, R. 33139 MOTICE TO THE CITY OF MIAMI SEACH SUILDING DEPARTMENT OF EMPLOYHERT AS SPECIAL INSPECTOR INDER THE FOREIGN SUILDING CODE  THOSE THE FOREIGN SUILDING CODE  THAT SEACH SEA	Secret Impacts to Refreshment Engineer, by Architect Secreted in the State of Refreshment in Market Secretaria (in Description).  Secreta Impacts for Party 120.  Secreta Impacts for Party 12	Special importion for State Board & Weichel Committee, PEC 2318.2 (By P.B. or B.A.) Special inspector for Traces over 35 heat larg or 6 feet high, PEC 2318.37.2.4.2 (By P.B. or B.A.) Special inspector for	A sections 1973.112, 23118.2, discussions 1973.112, 23118.2, discuss or Engineered Architect.  A baking they was baded near to deposit on the control and the control and they section to the control and they section to the control and they section to the control and the	CITY CONTROL TO THE VERY

L (wr) have been retained by Labora Example. up perform the Fords Building Code at the 1944 1947 Appleadage project of 5-23-05 (date). I am & Professional Engineer for Architect Remarks



The following and victures employed by this fam or me are

1. J.H. Steenings OFE.

Special Inspector for Parces, TPC 1472.1.1.2
Special Inspector for Parces, Red-Inspector for Parces, Muchanisms Special Inspector for Neithroad Meathers, Special Inspector for Tourses over 35 feet Special Inspector for Tourses Special Inspector for Tourses

I just will mally the Dity of Haywa Basch Building Daperhament of ony drawgue requireds

WOODM, ECCHTOR OF A Statements, P.S. Profession Control Statements Control Statements Control Statements Control Statement Control Stateme Remove all loves and spalling concrete using a light chipping hammer.
 Inspect exposed microx reminerly and and replace any seet damaged in crease of which the hammer is per Act 3112-90. Seed a best of the dispersers or 30 inch minimizen as to be so minimizen of 15 inches.
 Encodernes of rethe into existing concrete structures in the a minimizen of 9 inches and sitia 31 Get sproy is to be used.
 Sandbless crisings concrete structures in the a minimizen of 9 inches of Sandbless crisings grounded riths and cost with Annaires 110 or equivalent.
 Grante to original dimension.
 In progress inspectives will be performed and a final impact on myort will be forwarded upon completion. We have been retained by the owners of 1344 15° former, to provide special impartor arrives as defined in archive 105 of the F R C. The repairs are to be performed by Rebbeats Granie Service, under contract to the conset. The repairs will consist of the following. Gemie frysai no approxicmachy 120 lineal foct of reinforced concrete columns in approximately 250 lineal foct of reinforced concrete is beam.
 Guide reysai to approximately 250 lineal foct of reinforced concrete Chinde reysai to approximately 200 lineal foct of reinforced concrete grade beam. City of Misses Brach Buiking Department 1700 Convention Center Drive Misses Beach, Florida 13139 Arr: Building Official

JA SHEINGOED PAC STIBI PAC STIBI PAC STIBI 305 378 1244 1344 1246 TERR CUNITE REPAIR 15 TERR SULTH TWO STORY BUILDING EAST UNDERNEATH WALLS TO BE REPAIRED NURTH

