

NOR

10

SCALE 1"

Д

00

100

E 10(

4 õ

 \sim

4

0

Z

₹

ANTE.

FD DRILL

HOLE

9

€

œ

30

DR

OCEAN

<u>~ □ º</u>

PLANTER

COPYRIGHT 2016 LAWRENCE E. POWERS

TYPE OF SURVEY: AS-BUILT PREPARED FOR: SOBE USA LLC

CERTIFIED TO: A) SOBE USA LLC

PROJECT #: 9600CEAN

ORG.FIELD SURVEYED: NOV. 7, 2016 DATE DRAWN: NOV. 28, 2016 DATE SIGNED: NOV. 29, 2016

FLOOD ZONE: AE BASE FLOOD ELEV. 8' (NAVD 88) FEMA FIRM MAP # 12086C0319L

DATED SEPT 11, 2009 PANEL # 0319 SUFFIX L COMMUNITY #: 120651

MAP OF SURVEY

SUBJECT ADDRESS:

960 OCEAN DR MIAMI BEACH, FL 33139

LOTS 1 AND 2 BLOCK 14 OCEAN BEACH FLA. ADDITION No. 2 AS PER MAP OR PLAT THEREOF AS RECORDED IN PLAT BOOK 2 AT PAGE 56 OF THE PUBLIC RECORDS OF MIAMI-DADE COUNTY FLORIDA.

LEGAL DESCRIPTION SUPPLIED:

LAT: 25°46'49 O"N LONG: 80°07'51 4"W BEARING BASIS ASSUMED FOR ANGULAR DELINEATION ONLY

FOLIO #: 02-3234-008-0010 LOT SIZE: 13000 +/- SQFT

LAND USE: MIXED USE ENTERTAINMENT 6501 COMMERICAL

ADDITIONS OR DELETIONS TO THIS SURVEY MAP OR REPORT OTHER THAN THE SIGNING PARTY IS PROHIBITED WITHOUT WRITTEN CONSENT OF THE

RE-USE OF THIS SURVEY FOR PURPOSES OTHER THAN WHICH IT WAS INTENDED WITHOUT WRITTEN CONSENT FROM THE ENTITY IN WHICH IT WAS PREPARED FOR. WILL BE AT THE RE-USERS SOLE RISK AND WITHOUT LIABILITY TO THE SIGNING SURVEYORS OR ITS FIRM.

NOTHING HEREIN SHALL BE CONSTRUED TO GIVE ANY RIGHTS OR BENEFITS TO ANYONE OTHER THAN THOSE WHOM THE SURVEY WAS PREPARED FOR.

THIS MAP CONSIST OF 1 SHEET(S). WHEN MULTIPLE SHEETS COMPRISE THE PLAT OR MAP OF SURVEY NO SINGLE SHEET SHALL BE CONSIDERED FULL AND COMPLETE WITHOUT THE OTHER/S.

LANDS SHOWN HEREON WERE NOT ABSTRACTED BY THIS SURVEYOR FOR EASEMENTS AND/OR RIGHTS OF WAY OF RECORD.

THIS SURVEY HAS BEEN PREPARED FOR THE EXCLUSIVE USE OF THE ENTITIES NAMED HEREON. THE CERTIFICATION SHOWN HEREON DOES NOT EXTEND TO ANY UNNAMED PARTY.

THIS IS AN ABOVE GROUND SURVEY AND LOCATIONS ARE LIMITED TO VISIBLE IMPROVEMENTS ONLY. NO IMPROVEMENTS HAVE BEEN LOCATED EXCEPT AS SHOWN. THERE MAY BE ADDITIONAL ABOVE GROUND AND/OR UNDERGROUND UTILITIES / IMPROVEMENTS NOT SHOWN ON THIS SURVEY.

NO ABSTRACT OF TITLE, TITLE COMMITMENT, NOR RESULTS OF TITLE SEARCHES WERE FURNISHED TO THIS SURVEYOR. THERE MAY EXIST OTHER DOCUMENTS OF RECORD THAT WOULD AFFECT THIS PARCEL.

MEASUREMENTS SHOWN HEREON ARE IN U.S. SURVEY FEET AND DECIMALS

THE EXISTING MONUMENTATION AS SHOWN HEREON HAS BEEN HELD TO DEFINE THE PLAT AND RECORD BOUNDARY TITLE DESCRIPTIONS. SAID MONUMENTATION HAS BEEN DETERMINED TO BE THE BEST ACCEPTABLE EVIDENCE OF THE DEEDING INTENT OF THOSE AREAS INVOLVED. SAID EXISTING MONUMENTATION MAY OR MAY NOT HARMONIZE WITH STANDARD SECTIONALIZED LANDS LINES, OTHER RECORD PLAT BOUNDARIES OR LIMITS AND OTHER FEE TITLE DESCRIPTIONS ADJACENT TO THE AREA SHOWN HEREON.

THERE MAY BE ADDITIONAL RESTRICTIONS AND/OR OTHER MATTERS THAT ARE NOT SHOWN ON THIS PLAT OF SURVEY THAT MAY BE FOUND IN THE PUBLIC RECORDS OF THIS COUNTY.

THE TERM CERTIFIED AS USED ON THIS PLAT, IS UNDERSTOOD TO BE THE PROFESSIONAL OPINION OF THIS SURVEYOR WHICH IS FORMULATED ON HIS BEST KNOWLEDGE AND INFORMATION, AND AS SUCH, IT DOES NOT CONSTITUTE A GUARANTEE OR WARRANTY, EITHER EXPRESSED OR IMPLIED. THE SURVEY DEPICTED HERE IS NOT COVERED BY PROFESSIONAL LIABILITY INSURANCE.

LEGEND: (CM) -x-ENC (WV) (CLF) (CPP) FP&L ESM'T

CONC. SIDEWALK 5.3 --IN CONC BEARING BASIS 4 9.8 73.4 0.3 ENTRANCE EDGE OF BUILDING 30.2 COLUMNS ALONG LOT LINE FIELD MEASURES . 33.96 DEED PLAT THE EDISON 0.3(R/W) RIGHT-OF-WAY 20.00 → ELEV NGVD NON RADIAL LINE IRON PIPE OCK 4 STORY MASONRY IRON ROD OT 100R CONCRETE MONUMENT HOTEL ELECTRIC LINE CAFI (4.53) DENOTES ELEVATION ADDRESS # 960 TELEPHONE LINE മ FENCE FIRE HYDRANT 0 ENCROACHMENT WATER VAVLE WATER METER 47 유 CHAIN LINK FENCE 35.2 12.1 SECONDS SYMBOL WOOD POWER POLE 4 CONCRETE POWER POLE CANOPY COVERED BAR FLORIDA POWER & LIGHT EASEMENT ≶ MINUTE SYMBOL <u>ရ</u> DEGREES SYMBOL \vdash 7.6 WEST GUY ANCHOR 0 EAST Õ 20.0 BLDG BUILDING 00 39.0 (FD) FOUND A/C'S & SET IRON ROD ELECT. ROOM FOUND IRON ROD P SET CONCRETE MONUMENT COVERED MASONRY LOT 2 BLOCK 14 FOUND CONCRETE MONUMENT COLUMNS (PC) POINT OF CURVATURE 20.0 (PT) POINT OF TANGENCY CONC. PATIO A 1 INCH IRON PIPE OR STAIRS 5/8 INCH REBAR WITH A PLASTIC CAP LABELED LS 0.1 20.1 5505 IS SET WHERE SET IS 29.9 CLEAR INDICATED ON THIS PLAT. 6.4 4" FRAME 11.2 --- -WALL W/ DOOR

MASONRY WALL

LOT 3

10TH ST (50' R/W)(P)

N79°12'13"W 130.00'(P)

MASONRY WALL

S79°12'13"E 130.00'(P)

— 34.6 ·

MASONRY WALL

CENTERLINE R/W

CONC. CURB & GUTTER -

LAWRENCE E.POWERS P. O. BOX 48026

> ST. PETERSBURG, FL 33743-8026 P: 727-537-9895

E: SURVEYINGSTPETE@GMAIL.COM

WWW.SURVEYINGSTPETE.COM 4996 MIRAMAR DR UNIT 6207 ST PETERSBURG, FL 33708 AS-BUILT SURVEY

DATE: NOV. 29, 2016 PROJECT #: 9600CEAN

PREPARED FOR THE SOLE AND EXCLUSIVE USE FOR CONOPY PERMIT

FD #5

REBAR


FD N&W

AMTENCE E PON ... UNDERSIGNED HEREBY CEREA TRUE REPRESENTATION OF JUNEAU MAND FIELD SURVEY MADE PERVISION \$505 MEETS UNDER MY DIRECTION AND SPERISION OF EXCEEDS THE STANDARDS OF PRAFOR RECORD SURVEYS IN THE TATE OF FLORIDA SUBJECT TO ALL NOTES SHOWN HEREON. NOT DS OF PRACTICE OF FLORIDA AS PER

HEREON. NOT VALID STATEOF L FLORNDA

9







ADJACENT SITE - SOUTH SIDE: THE BREAKWATER

Date of Photo: November 2016 940 Ocean Dr, Miami Beach, FL 33139







Date of Photo: (Top) November 2016 (Right) January 2017 1020 Ocean Dr, Miami Beach, FL 33139






STREET ELEVATIONS

Date of Photo: January 2017 (Top) Looking East from the Edison (Right) Looking South from The Clevelander





THE EDISON EAST ELEVATION PHOTOS









THE EDISON
COURTYARD - WEST ELEVATION PHOTOS











THE EDISON - EXISTING SOUTHEAST CORNER AWNING / UMBRELLA CONDITION AT BUILDING

THE EDISON - EXISTING NORTHEAST CORNER AWNING / UMBRELLA CONDITION AT BUILDING

Date of Photo: January 2017

** NOTE: THE NON-STRUCTURAL COLUMNS AND FAUX-GREEN COLUMN CLADDING AT ENTRY, ALONG WITH SIDEWALK HEATERS ARE CURRENTLY BEING REMOVED IN RESPONSE TO CERTIFICATE OF APPROPRIATENESS VIOLATIONS NOTED ON JANUARY 5TH, 2017. THESE PICTURES SHOWN HERE WERE TAKEN BEFORE THE REMOVAL.

**NOTE: THE NEW AWNING SYSTEM THAT IS BEING PROPOSED WILL SOLELY REPLACE ALL EXISTING AWNINGS AND UMBRELLAS ON THE EAST ELEVATION, IN ORDER TO REMOVE VISUAL CLUTTER FROM THE SIDEWALK AND BUILDING FACADE.




THE EDISON - EXISTING NORTHEAST CORNER CONDITION UNDER EXISTING UMBRELLAS/AWNING

Date of Photo: January 2017


** NOTE: THE NON-STRUCTURAL COLUMNS AND FAUX-GREEN COLUMN CLADDING AT ENTRY, ALONG WITH SIDEWALK HEATERS ARE CURRENTLY BEING REMOVED IN RESPONSE TO CERTIFICATE OF APPROPRIATENESS VIOLATIONS NOTED ON JANUARY 5TH, 2017. THESE PICTURES SHOWN HERE WERE TAKEN BEFORE THE REMOVAL.

**NOTE: THE NEW AWNING SYSTEM THAT IS BEING PROPOSED WILL SOLELY REPLACE ALL EXISTING AWNINGS AND UMBRELLAS ON THE EAST ELEVATION, IN ORDER TO REMOVE VISUAL CLUTTER FROM THE SIDEWALK AND BUILDING FACADE.






EXISTING EAST ELEVATION SCALE: N.T.S





EXISTING SOUTH ELEVATION SCALE: N.T.S



EXISTING SITE PLAN SCALE: N.T.S