


**TREE DISPOSITION PLAN**  
SCALE: 3/32" = 1'-0"



**EXISTING TREE LIST:**

No.	BOTANICAL NAME	COMMON NAME	DBH (")	Ht. (')	Sp. (')	Condition	Disposition	DBH loss (")	Comments
1	Cocos Nucifera	Coconut Palm	Triple Tk	20	10	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
2	Ptychosperma Elegans	Alexander Palm	20	25	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
3*	Lycium Latifolium	Wild Tamarind	20	25	30	Poor	Remove	40	Specimen size - Mitigation doubled
4	Ptychosperma Elegans	Alexander Palm	4	20	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
4a	Ptychosperma Elegans	Alexander Palm	4	20	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
5	Mangifera indica	Mango Tree	8	20	8	Poor	Remove	8	
6	Ptychosperma Elegans	Alexander Palm	4	15	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
6a	Ptychosperma Elegans	Alexander Palm	4	18	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
7	Ptychosperma Elegans	Alexander Palm	4	20	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
7a	Ptychosperma Elegans	Alexander Palm	4	15	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
7b	Ptychosperma Elegans	Alexander Palm	4	22	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
7c	Ptychosperma Elegans	Alexander Palm	4	20	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
8	Roystonea Elata	Royal Palm	24	40	15	Fair	Remain	0	
9	Unknown								Not accessible
9a	Bambusa spp.	Bambo Clump	Multi	20	10	Fair	Remove	0	Does not require permitting / replacement
10	Not on site								
11	Not on site								
11a	Wodyetia Bifurcata	Foxtail Palm	Triple Tk	13	12	Fair	Remove	0	Does not require permitting / replacement
12	Murraya Paniculata	Orange Jasmine				Poor	Remove	0	Overgrown shrub
12a	Sabal Palmetto	Sabal Palm		6	5	Fair	Remove	0	Does not require permitting / replacement
13	Roystonea Elata	Royal Palm	24	40	15	Fair	Remain	0	
14	Ptychosperma Elegans	Alexander Palm	4	25	5	Fair	Remove	0	Requires replacement with (1) 12" x 2" DBH tree
15*	Quercus Virginiana	Live Oak	12	25	25	Good	Remain	0	
16*	Quercus Virginiana	Live Oak	9	25	25	Good	Remain	0	
Total DBH loss:								48	

\* Indicates ROW tree  
 Total Palm trees to be removed: (11) 12" Ht. x 2" DBH trees  
 Palm tree replacement required: (11) 12" Ht. x 2" DBH trees  
 Total DBH proposed for removal: 48"  
 Total Mitigation trees required: (16) 12" Ht. x 2" DBH x 6' Sp. trees OR (8) 16" Ht. x 4" DBH x 8' Sp. trees

No.	REVISIONS	BY

**NOTICE:**  
 GENERAL CONTRACTOR: YOUR RESPONSIBILITY TO WORK TOGETHER WITH THE ARCHITECTURAL & ENGINEERING DRAWINGS. IF ANY DISCREPANCIES APPEAR, CALL THE ARCHITECTS & THE ENGINEERS OF RECORD BEFORE CONTINUING ANY WORK.

PROPOSED NEW RESIDENCE FOR:  
**MR. JORGE FERNANDEZ**  
 LOCATED AT:  
 13170 S.W. 128th Street  
 MIAMI BEACH, FL 33140

**CALIL ARCHITECTS**  
 1728 CORAL WAY, SUITE-702 MIAMI, FLORIDA 33145  
 AA 26001949 PHONE: (305) 860-8600 FAX: (305) 860-8602  
 EDUARDO A. CALIL ARCHITECTS, INC. MIAMI, FLORIDA 33145  
 WWW.CALILARCHITECTS.COM



DESIGNING BEAUTIFUL SPACES  
**LLA LAURA LLERENA & ASSOCIATES**  
 LANDSCAPE ARCHITECTURE  
 13170 S.W. 128th Street, Suite 207, Miami, FL 33186  
 Tel: 305-256-1199 / Fax: 305-256-1155  
 www.llerena-associates.com



DRAWINGS AND SPECIFICATIONS AS INSTRUMENTS OF SERVICE ARE AND SHALL REMAIN THE PROPERTY OF THE LANDSCAPE ARCHITECT. WHENEVER THE PROJECT FOR WHICH THEY ARE MADE IS EXECUTED OR NOT, THEY ARE NOT TO BE USED BY OWNER ON OTHER PROJECTS EXCEPT BY AGREEMENT IN WRITING AND WITH APPROPRIATE COMPENSATION TO THE LANDSCAPE ARCHITECT.

SHEET No.  
**EX-1**  
 DRAWN LR  
 CHECKED LMLH  
 DATE APRIL 2021  
 SCALE SHOWN  
 JOB No.