

333 JEFFERSON AVENUE – PROPERTY HISTORY



343 Jefferson Avenue (front), 1955

343 Jefferson Avenue (front)

- Original construction 1922
 - Architect Rowan & Schaffer
 - Not listed in City Directory until 1927
 - Three apartment units
- Remodeled into four apartments 1948
 - Architect August Swarz
 - Known as Bonnie Apartments




343 Jefferson Avenue (rear), 1955

343 Jefferson Avenue (rear)

- Original construction 1922
 - Architect unknown
 - Occupied by commercial enterprises
- Converted into six efficiency apartments 1952
 - Architect T. Hunter Henderson

SUE 2 4 AUTO BOO'S RED (14)

Sanborn Map, 1947



Aerial Photo, 1952

343 Jefferson Avenue


- Front and rear buildings originally connected
- May have been separated in 1948
- Were definitely separated by 1952



333 Jefferson Avenue (front), 1955

333 Jefferson Avenue (front)

- Original construction 1939
 - Architect H. George Fink
 - Four apartments and four hotel rooms
 - Hotel rooms converted into two apartments 1955



333 Jefferson Avenue (rear), 1955

333 Jefferson Avenue (rear)

- Original construction 1955
 - Architect T. Hunter Henderson
 - Six efficiency apartments









333 & 343 Jefferson Avenue, 1955

333 Jefferson Avenue

- Under single ownership 1955
- Staggered ownership 1958-1987
- Single ownership 1987-2016
- United into one parcel 2017
- Only maintenance and minor improvements since 1955

Architects

- Rowan & Schaffer
 - No information found
- H. George Fink (1890-1975)
 - One of the original architects of Coral Gables
 - Created the term "Mediterranean" to describe Florida architecture, but never added "Revival"
 - Designed mostly in Mediterranean style
- T. Hunter Henderson (1894-1976)
 - Designed in Art Deco, Streamline, Mediterranean Revival and Modern styles



343 Jefferson Avenue, (1955)





343 Jefferson Avenue, (Proposed)





333 Jefferson Avenue, (1955)

333 Jefferson Avenue, (Proposed)



333 JEFFERSON AVENUE – INSPECTION HISTORY

Understanding the meaning of a "Partial Pass" Inspection"?

- As you progress in construction of an existing and deteriorated building, conditions uncovered at the site requires revisions and approval, and
- When a permit covers multiple buildings a "partial" is issued to that specific building understanding that related inspections will follow to the pending buildings.

History:

In 2020, the Florida Americans with Disabilities Accessibility Act, Section 553-509, waiver was granted by the State. This section requires vertical accessibility to all levels. The waiver was granted based on substantial financial costs. The applicant is still required to comply and provide access to ground level structures in compliance with the American with Disabilities Act of 1990.

- **❖ 2/10/21 PLUMBING INSPECTION "Correction Required"**.
 - Requested that the foundation inspection must be passed.
- 2/10/21 BUILDING Window Inspection: "Partial Pass" buildings 345 and 337
- ❖ 2/10/21 BUILDING INSPECTION Building Foundation
 - Inspector requested footers to be open for inspection.

- ❖ 2/11/21 BUILDING INSPECTION Bldg. columns "Re-inspection". Columns added to the plans because of the condition found at the "site" was unidentified at the time of plan submittal. Stucco on the south side of bldg. 343 had excessive deterioration and the stucco completely dilapidated and windows needed reinforcement.
- 2/24/21 Structure Revision pages S-06.1 revision to the front and rear building 343 and 337.

- ❖ 3/19/21 BUILDING Columns Inspection "Partial Pass" <u>Bldg. 343</u> reinforce the second floor completely. First floor reinforcement upon completion of the plumbing underground. The first level the floor had to saw cut to accommodate the plumbing work.
- ❖ 3/24/21 BUILDING Bldg. Columns Inspection "Partial Pass"
 - Re-inspection of building 345- footer and foundation

- ❖ 3/24/21 BUILDING Plumbing Undergrounds Inspection "Partial Pass." Rear buildings 334 and 345
- ❖ 3/24/21 BUILDING Bldg. Foundation Inspection "Partial Pass" bldg. 345 footer and wood joists passed.
- ❖ 5/21/21 BUILDING Bldg. Framing Inspection. "Re-inspection Required"
 - Inspector requested to pass all MEP rough before calling building inspections. Made all corrections began plumbing underground.

- ❖ 5/21/21 BUILDING Plumbing Undergrounds Inspection "Partial Pass."

 Rough underground for building 343 because the slab floor was reinforced and the underground plumbing was complete, and the slab re-poured. As we moved to bldg. 343, we realized that the wood joists and top beam was completely disintegrated and rotted by termites and the elements.
- ❖ 8/27/21 BUILDING Plumbing Underground Inspection. "Re-inspection Required." Inspection canceled on-site by the Plumber

❖ 9/8/21 BUILDING – Plumbing Underground Inspection. "Partial Pass." Underground building 333.

Note: Because the plumbing sanitary lines are gravity feed the rear building were complete first. The final connection is in the front of the building.

❖ 2/17/2022 BUILDING - Plumbing Underground Inspection. "Partial Pass."




333 JEFFERSON AVENUE –
STRUCTURAL CONDITIONS
-APPROVED DEMOLITION-APPROVED STRUCTURALS-REVISED STRUCTURAL & SHORING DRAWINGS-








333 JEFFERSON AVENUE – STRUCTURAL CONDITIONS





-APPROVED DEMOLITION BUILDING 343 & 337 - DATED 07/24/2020













-APPROVED STRUCTURALS BUILDING 343 & 337 – (ROOF JOIST REPLACEMENT IF NEEDED AND FILL CELLS)

DATED 7/24/2020




-APPROVED STRUCTURALS BUILDING 333— (STAIR REPLACEMENT AND WALLS REPLACEMENT)

DATED 7/24/2020




-APPROVED STRUCTURALS BUILDING 343 & 337 – (FILL CELLS ADDITION TO REINFORCE BUILDING)

DATED 3/10/2021




- STRUCTURAL REVISION BUILDING 333— (FIRST FLOOR AND SECOND FLOOR JOIST AND INTERIOR BEARING WALLS REPLACEMENT)

DATED 11/7/2021




- STRUCTURAL REVISION BUILDING 333— (FIRST FLOOR AND SECOND FLOOR JOIST AND INTERIOR BEARING WALLS REPLACEMENT)


DATED 11/7/2021



- STRUCTURAL REVISION BUILDING 343— (ROOF JOIST AND INTERIOR BEARING WALLS REPLACEMENT)



- SHORING PLAN BUILDING 333, FOR FIRST FLOOR AND SECOND FLOOR JOIST AND INTERIOR BEARING WALLS REPLACEMENT DATED 11/7/2021



- SHORING PLAN BUILDING 333, FOR FIRST FLOOR AND SECOND FLOOR JOIST AND INTERIOR BEARING WALLS REPLACEMENT DATED 11/7/2021