## **407 Lincoln Road**

--



Revision	# 2	(NG/2N	/20221
INCVISION	π <b>∠</b>	103/30/	20221

	COMMENTS	RESPONSES	
	HPB PLAN REVIEW COMMENTS		
	ZONING COMMENTS DATE: 09-30-2022	Reviewer: James Seiberling Ph	
Α	Clearly label all areas that are excluded from FAR. Sheet A1.00, existi mezzanine identify areas excluded from FAR. Sheet A.1.0, level 1, identify room; mezzanine level, mechanical rooms cour FAR except above the main roofline. Sheet A.11, identify all rooms at the roof level excluded from FAR.	SEE REVISED SHEETS A1.00, A1.03	
В	Provide proposed FAR diagrams for every floor, not just typical levels	SEE REVISED SHEETS A1.10, A1.11, A1.12, A 1.13	
	DEFICIENCIES IN PRESENTATION COMMENTS DATE: 09-30-2022	Reviewer: James Seiberling Ph	
Α	Staff has serious doubts that FPL will allow the transformer to remain below grade. Do you have written correspondence from FPL indicating that the transformer can remain?		
В	Provide the same level of detail for the existing lobby elevations as the proposed. Indicate existing/proposed materials and finishes for existing and proposed elevations.	e SEE REVISED SHEETS A4.60, A4.61, A4.62	
С	Provide enlarged detailed exterior elevation drawings of the ground/mezzanine level.	SEE REVISED SHEETS A4.63, A4.64, A4.65	
	DESIGN/APPROPRIATENESS COMMENTS DATE: 09-30-2022	N/A	