

7871 EAST BUILDING

1 North Elevation - EXISTING UTILITIES
ASI 1 — 1/4" = 1'-0"



7871 EAST BUILDING

3 North Elevation - RELOCATED UTILITIES
ASI 1 — 1/4" = 1'-0"

BUILDING 7871: ALL ABANDONED EQUIPMENT TO BE REMOVED. NEW DOOR TO BE INSTALLED PER THE CONSTRUCTION DOCUMENTS. WATER LINE TO BE BURIED IN THE GROUND AND ELECTRICAL BOX MOVED TO THE LEFT OF THE OPENING TO NOT INTERFERE WITH THE DOOR/NEW LANDING. PATCH AND REPAIR THE FACADE TO MATCH EXISTING BRICK TEXTURE. PAINT FACADE PER CONSTRUCTION DOCUMENTS.



7861 EAST BUILDING

2 South Elevation- EXISTING UTILITIES
ASI 1 — 1/4" = 1'-0"



7861 EAST BUILDING

4 South Elevation - RELOCATED UTILITIES
ASI 1 — 1/4" = 1'-0"

BUILDING 7861: RELOCATE THE ELECTRICAL BOX ABOVE NEW AWNING. RELOCATE C/U CONDENSATE LINE TO THE RIGHT OF THE NEW LANDING. PATCH AND REPAIR THE FACADE TO MATCH EXISTING BRICK TEXTURE. NEW DOOR TO BE INSTALLED PER CONSTRUCTION DOCUMENTS. PAINT FACADE PER CONSTRUCTION DOCUMENTS.

THE TAMARA PEACOCK COMPANY Architects
1512 E Broward Blvd, Suite 102
Fort Lauderdale, FL 33301
Ph: 954-728-8000
Fax: 954-729-9225

PROJECT NAME:
MADELEINE VILLAGE APTS
7861 CRESPI BLVD
MIAMI BEACH, FL 33141

SHEET NAME:
UTILITIES RELOCATION

PROJ.: 19-0102
DATE: 6/7/2021
SHEET NO.: ASI 1

REVISION | REVISION DATE | ISSUED FOR

Tamara Peacock, R.A. License No. 12124

PRIN.: DESIGNER | DRAWN BY: AUTHOR
APPR.: APPROVER | REVIEW BY: CHECKER