## **Contractor Price Proposal Summaries - Category**

**Date:** 4/25/2019

**Work Order #:** 067120.00

Title: North Bay Road Pocket Park

Contractor: EZIQC - Team Contracting. Inc.

Contractor Number: FL04UG3-051716-TCI

**Job Order Value:** \$629,329.61

Proposal Name: Copy (Apr 25 2019 2:37PM) of North Bay Road Pocket Park

**Proposal Value:** \$629,329.61

To: Project Manager

**Rubber Surface** 

**Shade Structure** 

Steel Fence

Category LineTotal \$67,359.88 Concrete **Fence** 23855.9079 Miscellaneous 4847.1604 **Playground** 16980.3835 **Shades** 21676.4254 **Earthwork** \$37,862.14 **Fence** 5800.5839 **Playground** 27717.5581 **Shades** 2962.8458

From:

Contractor Project Manager

1381.1537 **Swales Electrical** \$11,849.41 **Finishes** \$12,385.19 **General Requirements** \$35,596.95 Irrigation \$21,554.49 Landscaping \$114,627.10 Masonry \$17,628.86 **Playground Assembly** \$30,092.64 **Plumbing** \$4,896.44

Grand Total: \$629,329.61

This work order proposal total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding of the line totals and sub-totals.

The Percent of NPP on this Proposal: 2.04

\$73,556.33

\$172,485.85

\$29,434.34

## **Contractor Price Proposal Details - Category**

**Date:** 4/25/2019

Work Order #: 067120.00

Title: North Bay Road Pocket Park

**Contractor:** EZIQC - Team Contracting. Inc.

Contractor Number: FL04UG3-051716-TCI

**Job Order Value:** \$629,329.61

Proposal Name: Copy (Apr 25 2019 2:37PM) of North Bay Road Pocket Park

**Proposal Value:** \$629,329.61

	CSI Number	Mod	UOM	Description	n					LineTotal
Cor	ncrete									
	Fence									
1	01 74 19 00-0036		CYM	Hauling On F	Paved Road	s, N	liles Over Initia	l 15 Miles		\$589.71
					Qty		Unit Price	Factor	Total	
				Installation	1095	Χ	\$0.39 X	1.3809	\$589.71	
		Contrac	ctor Notes:	Columns and	d Wall Fun.	Exc	avations			
2	03 11 13 00-0003		SF	Continuous F	ootings Fo	unda	ation Wood For	rmwork		\$1,765.48
					Qty		Unit Price	Factor	Total	
				Installation	373.83	Χ	\$3.42 X	1.3809	\$1,765.48	
		Contrac	ctor Notes:	Instalation W	all Footing					
3	03 11 13 00-0003	0001	MOD	For <1,000, A	Add					\$299.41
					Qty		Unit Price	Factor	Total	
				Installation	373.83	Χ	\$0.58 X	1.3809	\$299.41	
4	03 11 13 00-0004		SF	Pile Cap, Pie	r Or Spread	d Fo	otings Foundat	tion Wood I	Formwork	\$2,077.48
					Qty		Unit Price	Factor	Total	
				Installation	378	Χ	\$3.98 X	1.3809	\$2,077.48	
		Contrac	ctor Notes:	Column Foot	ting					
5	03 11 13 00-0004	0001	MOD	For <1,000, A	Add					\$360.17
					Qty		Unit Price	Factor	Total	
				Installation	378	Χ	\$0.69 X	1.3809	\$360.17	
6	03 21 11 00-0049		LF	#3, Grade 60	), Columns,	Ste	el Reinforceme	ent Bar		\$68.05
					Qty		Unit Price	Factor	Total	
				Installation	112	Χ	\$0.44 X	1.3809	\$68.05	
		Contrac	ctor Notes:	Columns Tie	s					
7	03 21 11 00-0051		LF	#5, Grade 60	), Columns,	Ste	el Reinforceme	ent Bar		\$678.57
					Qty		Unit Price	Factor	Total	
				Installation	420	Χ	\$1.17 X	1.3809	\$678.57	
		Contrac	ctor Notes:	Columns Ver	rtical Reinfo	rcer	ment			
8	03 21 11 00-0090		LF	#5, Grade 60	, Footings,	Ste	el Reinforceme	nt Bar		\$5,024.90
					Qty		Unit Price	Factor	Total	
				Installation	3400.8	Χ	\$1.07 X	1.3809	\$5,024.90	
		Contrac	ctor Notes:	Wall and Co	lumn Footii	ng R	Reinforcement			

	CSI Number	Mod	UOM	Description	1					LineTotal
Con	crete									
9	03 31 13 00-0018		CY	Direct Chute,	Place 3,0	00 P	SI Concrete Co	ontinuous F	ootings	\$4,855.69
					Qty		Unit Price	Factor	Total	
				Installation	28.53	Χ	\$123.25 X	1.3809	\$4,855.69	
		Contrac	tor Notes:	Wall Footing						
10	03 31 13 00-0018	0043	MOD	For >20 To 50	D, Add					\$96.13
					Qty		Unit Price	Factor	Total	
				Installation	28.53	Χ	\$2.44 X	1.3809	\$96.13	
11	03 31 13 00-0022		CY	Direct Chute,	Place 3,0	00 P	SI Concrete Sp	oread Footi	ngs	\$2,041.98
					Qty		Unit Price	Factor	Total	
				Installation	11	Χ	\$134.43 X	1.3809	\$2,041.98	
		Contrac	tor Notes:	Column Footi	ing					
12	03 31 13 00-0022	0042	MOD	For Up To 20	, Add					\$166.63
					Qty		Unit Price	Factor	Total	<u> </u>
				Installation	11	Χ	\$10.97 X	1.3809	\$166.63	
13	31 23 16 36-0007		CY	Excavation Fo	or Building	ı Fou	Indations And	Other Struc	tures Bv	\$412.30
.0	0. 20 .0 00 000.		0.				oe, Loader in L			ψ <u>2.</u> 00
					Qty		Unit Price	Factor	Total	
				Installation	73	Χ	\$4.09 X	1.3809	\$412.30	
		Contrac	tor Notes:	Wall Footing	36+Colum	n Fo	oting 37			
14	31 23 16 36-0007	0013	MOD	For >50 To 25	50, Add					\$165.32
					Qty		Unit Price	Factor	Total	
				Installation	73	Χ	\$1.64 X	1.3809	\$165.32	
15	31 23 16 36-0028		CY				emoval From E		For Building	\$304.43
				Touridations	Qty	Olia	Unit Price	Factor	Total	
				Installation	73	Х	\$3.02 X		\$304.43	
		Contrac	tor Notes:	Column and	_		****		<b>*</b>	
16	31 23 16 36-0028	0025	MOD	For >50 To 25						\$121.97
10	31 23 10 30 0020	0023	WOD	101 > 30 10 20	Qty		Unit Price	Factor	Total	Ψ121.51
				Installation	73	Х	\$1.21 X		\$121.97	
17	32 31 13 13-0027		VLF	Concrete Fill,			·		Ψ.Ξσ.	\$2,413.84
17	32 31 13 13-0027		VLF	Concrete Fill,	Qty	eter	Unit Price	Factor	Total	\$2,413.64
				Installation	142	~				
		Contrac	tor Notoo	Concrete for		X	\$12.31 X	1.3609	\$2,413.84	
		Contrac								
18	32 31 13 13-0027		VLF	Concrete Fill,		eter				\$2,413.84
					Qty	.,	Unit Price	Factor	Total	
		•		Installation	142	Х	\$12.31 X	1.3809	\$2,413.84	
		Contrac	tor Notes:	2' x 71 post						
							Subtot	al for Con	crete - Fence:	23855.9079
	Miscellaneous									
19	03 31 13 00-0005		SF	6" 3,000 PSI	Slab On G	rade	Concrete Slat	os Assembl	у	\$3,717.99
					Qty		Unit Price	Factor	Total	
				Installation	498.6	Χ	\$5.40 X	1.3809	\$3,717.99	
		Contrac	tor Notes:	Walkways+tra	ash can+F	R. Pre	essure Water F	ountain Sla	abs	

	CSI Number	Mod	UOM	Description	1					LineTotal
Con	ocrete									
20	03 31 13 00-0005	0164	MOD	For Up To 50	0. Add					\$1,129.17
					Qty		Unit Price	Factor	Total	* , -
				Installation	498.6	Х	\$1.64 X	1.3809	\$1,129.17	
							ubtotal for Co	ncrete - M	liscellaneous:	4847.1604
	1									
	Playground									
21	03 11 13 00-0009		LF	Up To 6" Higl	n Slab Edg	e an	d Block-Out W	ood Form	work	\$962.66
					Qty		Unit Price	Factor	Total	
				Installation	281.1	Χ	\$2.48 X	1.3809	\$962.66	
		Contrac	tor Notes:	Porous Conc	rete					
22	03 11 13 00-0009	0003	MOD	For Curved F	ormwork, A	Add				\$322.18
					Qty		Unit Price	Factor	Total	
				Installation	281.1	Χ	\$0.83 X	1.3809	\$322.18	
23	31 23 16 36-0007		CY	Excavation F	or Buildina	Fou	ndations And C	Other Struc	ctures Bv	\$2,406.39
							oe, Loader in L			
					Qty		Unit Price	Factor	Total	
				Installation	426.07	Χ	\$4.09 X	1.3809	\$2,406.39	
24	31 23 16 36-0007	0014	MOD	For >250 To	500, Add					\$358.90
					Qty		Unit Price	Factor	Total	
				Installation	426.07	Χ	\$0.61 X	1.3809	\$358.90	
25	31 23 16 36-0028		CY	Load Excess	Material F	or R	emoval From E	xcavation	For Building	\$1,776.85
							ctures by Mach			
					Qty		Unit Price	Factor	Total	
				Installation	426.07	Χ	\$3.02 X	1.3809	\$1,776.85	
26	31 23 16 36-0028	0026	MOD	For >250 To	500, Add					\$264.76
					Qty		Unit Price	Factor	Total	
				Installation	426.07	Χ	\$0.45 X	1.3809	\$264.76	
27	32 13 43 00-0002		SF	6" Thick Perv	ious Conci	rete	PavingIncludes	filter fabri	c. concrete.	\$6,766.94
			-	curing, finish,	and contro	ol joi	nts. Excludes e			<b>+</b> 2,12333
				and expansion		ng e				
				1	Qty	V	Unit Price	Factor	Total	
				Installation	736.9	X	\$6.65 X		\$6,766.94	
28	32 16 13 13-0009		LF	6" x 18" Cast		onci	rete Curb - Rac	lius		\$4,121.70
					Qty		Unit Price	Factor	Total	
				Installation	258.2	Х	\$11.56 X	1.3809	\$4,121.70	
							Subtotal for	Concrete	- Playground:	16980.3835
	Shades									
00				D.: 0 D:		. –				<b>0.1.700.01</b>
29	03 11 13 00-0004		SF	Pile Cap, Pie		d Fo	otings Foundat			\$4,732.04
				1 - 4 11 -21	Qty	V	Unit Price	Factor	Total	
		0 1		Installation	861	Χ	\$3.98 X	1.3809	\$4,732.04	
			tor Notes:							
30	03 11 13 00-0004	0001	MOD	For <1,000, A						\$820.38
					Qty		Unit Price	Factor	Total	
				Installation	861	Χ	\$0.69 X	1.3809	\$820.38	

	CSI Number	Mod	UOM	Description	LineTotal
Con	crete				
31	03 15 19 00-0051		EA	1" Diameter x 24" Length, Plain Steel, L-Type Cast In Place Anch Bolt	or \$872.51
				Qty Unit Price Factor To	tal
				Installation 44 X \$14.36 X 1.3809 \$872.	51
32	03 15 19 00-0051	0154	MOD	For Stainless Steel, Add	\$1,729.22
				Qty Unit Price Factor To	tal
				Installation 44 X \$28.46 X 1.3809 \$1,729.	22
33	03 15 19 00-0051	0155	MOD	For >10 To 50, Deduct	(\$18.84)
				Qty Unit Price Factor To	tal
				Installation 44 X (\$0.31) X 1.3809 (\$18.8	4)
34	03 21 11 00-0088		LF	#3, Grade 60, Footings, Steel Reinforcement Bar	\$935.95
				Qty Unit Price Factor To	
				Installation 1694.45 X \$0.40 X 1.3809 \$935.	95
		Contrac	ctor Notes:	Shades Footing	
35	03 21 11 00-0089		LF	#4, Grade 60, Footings, Steel Reinforcement Bar	\$269.62
				Qty Unit Price Factor To	•
				Installation 275 X \$0.71 X 1.3809 \$269.	62
		Contrac	ctor Notes:	Anchor Hoops Shades Footing	
36	03 21 11 00-0091		LF	#6, Grade 60, Footings, Steel Reinforcement Bar	\$2,795.76
				Qty Unit Price Factor To	
				Installation 1349.73 X \$1.50 X 1.3809 \$2,795.	76
		Contrac	tor Notes:	Shades Footing	
37	03 31 13 00-0022		CY	Direct Chute, Place 3,000 PSI Concrete Spread Footings	\$8,503.91
				Qty Unit Price Factor To	
				Installation 45.81 X \$134.43 X 1.3809 \$8,503.	91
		Contrac	ctor Notes:	Shades Footing	
38	03 31 13 00-0022	0043	MOD	For >20 To 50, Add	\$259.99
				Qty Unit Price Factor To	tal
				Installation 45.81 X \$4.11 X 1.3809 \$259.	99
39	31 23 16 36-0007		CY	Excavation For Building Foundations And Other Structures By Hydraulic Excavator, Backhoe, Loader in Loose Rock	\$254.89
				Qty Unit Price Factor To	tal
				Installation 45.13 X \$4.09 X 1.3809 \$254.	39
		Contrac	tor Notes:	Shades Fund. Excavation	
40	31 23 16 36-0007	0012	MOD	For >20 To 50, Add	\$191.32
				Qty Unit Price Factor To	tal
				Installation 45.13 X \$3.07 X 1.3809 \$191.	32
41	31 23 16 36-0028		CY	Load Excess Material For Removal From Excavation For Building	\$188.21
				Foundations and Other Structures by Machine	
				Qty Unit Price Factor To	tal
				Installation 45.13 X \$3.02 X 1.3809 \$188.	21
		Contrac	ctor Notes:	Shades Fund. Excavation	
42	31 23 16 36-0028	0024	MOD	For >20 To 50, Add	\$141.47
				Qty Unit Price Factor To	tal
				Installation 45.13 X \$2.27 X 1.3809 \$141.	47

	CSI Number	Mod	UOM	Description						LineTotal
Con	crete									
									rete - Shades:	21676.4254
							S	ubtotal fo	or Concrete:	\$67,359.88
Eart	thwork									
	Fence									
43	01 74 19 00-0035		CYM	Hauling On Pa	aved Roa	ds, F	irst 15 Miles			\$877.01
					Qty		Unit Price	Factor	Total	
				Installation	1095	Χ	\$0.58 X	1.3809	\$877.01	
		Contracto	or Notes:	Columns and	Wall Fund	d. Ex	cavations			
44	01 74 19 00-0035		CYM	Hauling On Pa	aved Roa	ds, F	irst 15 Miles			\$877.01
					Qty		Unit Price	Factor	Total	
				Installation	1095	Х	\$0.58 X	1.3809	\$877.01	
		Contracto	or Notes:	73 CY x 15 m	iles Colun	nns a	and Wall			
45	01 74 19 00-0036		CYM	Hauling On Pa	aved Roa	ds, M	liles Over Initia	l 15 Miles	,	\$589.71
					Qty		Unit Price	Factor	Total	
				Installation	1095	Х	\$0.39 X	1.3809	\$589.71	
		Contracto	or Notes:	Columns and	Wall 15 n	niles	added			
46	01 74 19 00-0036		CYM	Hauling On Pa	aved Roa	ds, N	liles Over Initia	l 15 Miles		\$1,171.35
					Qty		Unit Price	Factor	Total	
				Installation	2175	Х	\$0.39 X	1.3809	\$1,171.35	
		Contracto	or Notes:	145 CY x 15 r						
47	32 11 16 16-0009		SY	12" Crushed A		Bas				\$2,285.51
					Qty	.,	Unit Price	Factor	Total	
		0	NI 4	Installation	78.07	Х	\$21.20 X	1.3809	\$2,285.51	
		Contracto	or Notes:	Columns and	waii					
							Subtota	l for Earth	work - Fence:	5800.5839
	Playground									
48	01 74 19 00-0035		CYM	Hauling On Pa	aved Roa	ds, F	irst 15 Miles			\$853.12
					Qty		Unit Price	Factor	Total	
				Installation	1065.17	′ X	\$0.58 X	1.3809	\$853.12	
		Contracto	or Notes:	Play surface+	Porous C	onc	<i>⊦Walkway</i> s			
49	01 74 19 00-0035		CYM	Hauling On Pa	aved Roa	ds, F	irst 15 Miles			\$5,118.73
					Qty		Unit Price	Factor	Total	
				Installation	6391.05	X	\$0.58 X	1.3809	\$5,118.73	
		Contracto	or Notes:	426.07 CY x 1	5 miles					
50	01 74 19 00-0035		CYM	Hauling On Pa	aved Roa	ds, F	irst 15 Miles			\$5,118.73
					Qty		Unit Price	Factor	Total	
				Installation	6391.05	<b>У</b>	\$0.58 X	1.3809	\$5,118.73	
51	01 74 19 00-0036		CYM	Hauling On Pa	aved Roa	ds, M	liles Over Initia	l 15 Miles		\$573.65
					Qty		Unit Price	Factor	Total	
				Installation	1065.17	X	\$0.39 X	1.3809	\$573.65	
		Contracto	or Notes:	Play surface+	Porous C	onc	<i>⊦Walkway</i> s			

	CSI Number	Mod	UOM	Description	n					LineTotal
Eart	hwork									
52	01 74 19 00-0036		CYM	Hauling On F	Paved Road	ls, N	liles Over Initia	l 15 Miles		\$3,441.91
					Qty		Unit Price	Factor	Total	
				Installation	6391.05		\$0.39 X	1.3809	\$3,441.91	
		Contracto	or Notes:	426.07 CY x						
53	01 74 19 00-0036		CYM	Hauling On F		ls, N	liles Over Initia			\$3,441.91
					Qty	.,	Unit Price	Factor	Total	
				Installation	6391.05		\$0.39 X	1.3809	\$3,441.91	
54	32 11 16 16-0007		SY	6" Crushed A		Base		_		\$9,143.04
					Qty		Unit Price	Factor	Total	
		Contract	au Niataa.	Installation	639.1	Χ	\$10.36 X	1.3809	\$9,143.04	
				Playground						
55	32 11 16 16-0007	0010	MOD	For Limestor				<u> </u>	<del> </del>	(\$891.36)
				Installation	Qty	v	Unit Price	Factor	Total	
					639.1	X	(\$1.01) X	1.3609	(\$891.36)	
56	32 11 16 16-0007	0012	MOD	For >500 To			Harris Baran	Feeten	T-1-1	\$917.83
				la stallation	Qty	v	Unit Price	Factor	Total	
				Installation	639.1	Х	\$1.04 X		\$917.83	
							Subtotal for E	arthwork	- Playground:	27717.5581
	Shades									
57	01 74 19 00-0035		CYM	Hauling On F	Paved Road	ls, F	irst 15 Miles			\$542.18
					Qty		Unit Price	Factor	Total	
				Installation	676.95	Χ	\$0.58 X	1.3809	\$542.18	
		Contracto	or Notes:	Shades Fund	d. Excavatio	on				
			0.44							<b>^-</b>
58	01 74 19 00-0035		CYM	Hauling On F		ls, F		Fasta:	Tatal	\$542.18
				Installation	Qty 676.95	V	Unit Price \$0.58 X	Factor	Total \$542.18	
		Contracto	or Notes	45.13 CY x 1		^	φυ.36 A	1.3609	<b>Ф</b> 342.16	
<u></u>	04.74.40.00.0000	Oomitacti				la N	lilaa Oosaa laitia	LAT Miles		<b>\$20.4.57</b>
59	01 74 19 00-0036		CYM	Hauling On F	Qty	is, iv	liles Over Initia Unit Price	Factor	Total	\$364.57
				Installation	676.95	x	\$0.39 X		\$364.57	
		Contracto	or Notes:	Shades Fund			Ψ0.00 Λ	1.0000	ψου-ι.οτ	
				15 miles add						
60	01 74 19 00-0036		CYM	Hauling On F	Paved Road	ls, N	liles Over Initia	l 15 Miles		\$364.57
					Qty		Unit Price	Factor	Total	
				Installation	676.95	Χ	\$0.39 X	1.3809	\$364.57	
		Contracto	or Notes:	45.13 CY x 1	5 miles					
61	32 11 16 16-0009		SY	12" Crushed	Aggregate	Bas	e Course			\$1,149.34
					Qty		Unit Price	Factor	Total	
				Installation	39.26	Χ	\$21.20 X	1.3809	\$1,149.34	
		Contracto	or Notes:	Shades						
							Subtotal f	or Earthy	vork - Shades:	2962.8458
	Swales									

	CSI Number	Mod	UOM	Description						LineTotal
Ear	thwork									
62	01 74 19 00-0035		CYM	Hauling On Pa	ved Road	ds, Fi	rst 15 Miles			\$523.80
					Qty		Unit Price	Factor	Total	
				Installation	654	Χ	\$0.58 X	1.3809	\$523.80	
		Contracto	r Notes:	Swales 46.3 x	15 miles	Adde	ed			
63	01 74 19 00-0036		CYM	Hauling On Pa	ved Road	ds, M	iles Over Initia	l 15 Miles		\$352.21
					Qty		Unit Price	Factor	Total	
				Installation	654	Χ	\$0.39 X	1.3809	\$352.21	
		Contracto	r Notes:	Swales 46.3 x	15miles					
64	31 23 16 33-0009		CY	Cutting, Shapi Excavation by		ough	Grading Existi	ing Elevatio	ns For Bulk	\$186.64
					Qty		Unit Price	Factor	Total	
				Installation	43.6	Χ	\$3.10 X	1.3809	\$186.64	
		Contracto	r Notes:	Swales						
65	31 23 16 36-0028		CY	Load Excess N Foundations a					For Building	\$181.83
					Qty		Unit Price	Factor	Total	
				Installation	43.6	Χ	\$3.02 X	1.3809	\$181.83	
		Contracto	r Notes:	Swales						
66	31 23 16 36-0028	0024	MOD	For >20 To 50	, Add					\$136.67
					Qty		Unit Price	Factor	Total	•
				Installation	43.6	Χ	\$2.27 X	1.3809	\$136.67	
							Subtotal	for Earthw	ork - Swales:	1381.1537
							Su	btotal for	Earthwork:	\$37,862.14
Ele	ctrical									
67	26 05 19 16-0279		MLF	#12 AWG Cab Stranded, Place		THH		Volt Coppe	r, Single	\$494.67
					<del>500 III 00</del>	nduit				
					Qty	nduit	Unit Price	Factor	Total	
				Installation		nduit X			Total \$494.67	
68	26 05 19 16-0280		MLF	Installation #10 AWG Cab Stranded, Place	Qty 0.95 ole - Type	X THH	Unit Price \$377.08 X N-THWN 600	1.3809	\$494.67	\$65.81
68	26 05 19 16-0280		MLF	#10 AWG Cab	Qty 0.95 ole - Type	X THH nduit	Unit Price \$377.08 X N-THWN 600	1.3809 Volt Coppe	\$494.67	\$65.81
68	26 05 19 16-0280		MLF	#10 AWG Cab	Qty 0.95 ole - Type ced In Co	X THH nduit	Unit Price \$377.08 X N-THWN 600	1.3809 Volt Coppe Factor	\$494.67 r, Single	\$65.81
68	26 05 19 16-0280 26 05 26 00-0099		MLF	#10 AWG Cab Stranded, Place	Qty 0.95 ole - Type ced In Cor Qty 0.1	X THH nduit	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X	1.3809 Volt Coppe Factor 1.3809	\$494.67 r, Single	\$65.81 \$93.24
				#10 AWG Cab Stranded, Place Installation	Qty 0.95 ole - Type ced In Cor Qty 0.1	X THH nduit	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X	1.3809 Volt Coppe Factor 1.3809	\$494.67 r, Single	
				#10 AWG Cab Stranded, Place Installation	Qty 0.95 ole - Type ced In Col Qty 0.1 x 10' Lon	X THH nduit	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X pper-Clad Grou	1.3809 Volt Coppe Factor 1.3809 und Rods Factor	\$494.67 r, Single Total \$65.81	
				#10 AWG Cab Stranded, Place Installation 5/8" Diameter	Qty 0.95 ble - Type ced In Cor Qty 0.1 x 10' Lone Qty 1	X THH nduit X g Col	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X pper-Clad Grot Unit Price \$67.52 X	1.3809 Volt Coppe Factor 1.3809 und Rods Factor	\$494.67 r, Single  Total \$65.81	\$93.24
69	26 05 26 00-0099		EA	#10 AWG Cab Stranded, Place Installation 5/8" Diameter	Qty 0.95 ble - Type ced In Cor Qty 0.1 x 10' Lone Qty 1	X THH nduit X g Col	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X pper-Clad Grot Unit Price \$67.52 X	1.3809 Volt Coppe Factor 1.3809 und Rods Factor	\$494.67 r, Single  Total \$65.81	
69	26 05 26 00-0099		EA	#10 AWG Cab Stranded, Place Installation 5/8" Diameter	Qty 0.95 ble - Type ced In Cor Qty 0.1 x 10' Lon Qty 1	X THH nduit X g Col	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X pper-Clad Grou Unit Price \$67.52 X	1.3809 Volt Coppe Factor 1.3809 und Rods Factor 1.3809 Factor	\$494.67 r, Single  Total \$65.81  Total \$93.24	\$93.24
69	26 05 26 00-0099		EA	#10 AWG Cab Stranded, Place Installation 5/8" Diameter Installation 5/8" Bronze G	Qty 0.95  ole - Type ced In Cor Qty 0.1  x 10' Lone Qty 1  round Roo Qty 1  -5/8" Wide	X THH nduit X g Co X d Cla	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X pper-Clad Grou Unit Price \$67.52 X Imp Unit Price \$13.58 X	1.3809 Volt Coppe Factor 1.3809 und Rods Factor 1.3809 Factor 1.3809	\$494.67 r, Single  Total \$65.81  Total \$93.24  Total \$18.75	\$93.24
69 70	26 05 26 00-0099 26 05 26 00-0147		EA	#10 AWG Cab Stranded, Place Installation 5/8" Diameter Installation 5/8" Bronze G Installation >2' Length x 1	Qty 0.95  ole - Type ced In Cor Qty 0.1  x 10' Lone Qty 1  round Roo Qty 1  -5/8" Wide	X THH nduit X g Co X d Cla	Unit Price \$377.08 X N-THWN 600 Unit Price \$476.57 X pper-Clad Grou Unit Price \$67.52 X Imp Unit Price \$13.58 X	1.3809 Volt Coppe Factor 1.3809 und Rods Factor 1.3809 Factor 1.3809	\$494.67 r, Single  Total \$65.81  Total \$93.24  Total \$18.75	\$93.24 \$18.75

	CSI Number	Mod	UOM	Description						LineTotal
Elec	ctrical									
72	26 05 29 00-0111		EA	2" Diameter, 3 Clamp For Un			Steel, Standard	Pipe And	Rigid Conduit	\$265.69
					Qty		Unit Price	Factor	Total	
				Installation	20	Χ	\$9.62 X	1.3809	\$265.69	
73	26 05 33 13-1750		LF	3/4" Schedule Couplings, Dir			Chloride (PVC)	Conduit W	ith Glued	\$412.78
					Qty		Unit Price	Factor	Total	
				Installation	188	Χ	\$1.59 X	1.3809	\$412.78	
74	26 09 23 00-0431		EA				olt AC, Occupa n (Sensor Switc			\$124.57
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$90.21 X	1.3809	\$124.57	
75	26 09 23 00-0432		EA				77 Volt AC, Octor			\$254.47
					Qty		Unit Price	Factor	Total	
				Installation	4	Χ	\$46.07 X	1.3809	\$254.47	
76	26 24 16 00-0172		EA				Capacity, Main			\$812.18
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$588.15 X	1.3809	\$812.18	
		Contrac	ctor Notes:	100A Meter C	an					
77	26 24 16 00-0205		EA				Capacity, Main DC, 3 Wire, 1 I			\$2,139.94
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$1,549.67 X	1.3809	\$2,139.94	
78	26 24 16 00-0205	0046	MOD	For Hinged Do	or-In-Do	or Wi	th Yale 5116 V	Vith Rosette	e, Add	\$452.94
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$328.00 X	1.3809	\$452.94	
79	26 27 26 00-0092		EA	20 Amp, 2 Pol Receptacle (H			Volt, Watertig	ht Pin And	Sleeve	\$192.30
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$139.26 X	1.3809	\$192.30	
		Contrac	ctor Notes:	GFIC						
80	26 28 16 00-0362		EA		l Non-Fu		hase, 4 Wire, 4 NEMA 4, 4X 0			\$2,025.95
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$1,467.12 X	1.3809	\$2,025.95	
81	31 23 16 13-0007		CY	Excavation Fo excess materia			y Hand In Soill			\$823.15
					Qty		Unit Price	Factor	Total	
				Installation	15	Х	\$39.74 X	1.3809	\$823.15	
82	32 31 13 13-0010		VLF	12" Diameter I	Hole. Au	er B	y Machine Fen	ce Post Ho	le In Soil	\$136.54
			- <del>-</del>		Qty	,	Unit Price	Factor	Total	Ţ.55.61
					,		\$8.24 X		\$136.54	

	CSI Number	Mod U	OM	Description	)					LineTotal
Elec	ctrical									
83	32 31 13 13-0031	V	/LF	Concrete Fill,	36" Diame	eter I	Hole			\$531.59
					Qty		Unit Price	Factor	Total	
				Installation	12	Χ	\$32.08 X	1.3809	\$531.59	
84	01 22 20 00-0010	ŀ	HR	ElectricianFor			uded in the Cor	nstruction <sup>-</sup>	Task	\$1,072.68
					Qty		Unit Price	Factor	Total	
				Installation	16	Χ	\$48.55 X	1.3809	\$1,072.68	
		Contractor N	lotes:	To work and	connect to	exis	ting equipment	t.		
							Sı	ubtotal fo	or Electrical:	\$11,849.41
Fini	shes									
85	09 23 13 00-0004	I	LF	Vinyl Expande	ed Flange	Casi	ing Bead For P	laster App	lications	\$1,201.71
					Qty		Unit Price	Factor	Total	
				Installation	444	Χ	\$1.96 X	1.3809	\$1,201.71	
86	09 24 23 00-0004	;	SF	Two Coat Tro Interior or ext			Scratch/Finish	Excludes I	ath and felt.	\$7,016.56
					Qty		Unit Price	Factor	Total	
				Installation	1946.8	Χ	\$2.61 X	1.3809	\$7,016.56	
87	09 91 13 00-0089		SF	Paint Exterior	Stucco W	alls,	1 Coat Primer,	, Brush/Ro	ller Work	\$1,344.17
					Qty		Unit Price	Factor	Total	
				Installation	1946.8	Χ	\$0.50 X	1.3809	\$1,344.17	
88	09 91 13 00-0091		SF	Paint Exterior	Stucco W	alls,	2 Coats Paint,	Brush/Rol	ler Work	\$2,822.75
					Qty		Unit Price	Factor	Total	
				Installation	1946.8	Χ	\$1.05 X	1.3809	\$2,822.75	
							S	Subtotal f	or Finishes:	\$12,385.19
Gen	eral Requirements									
89	01 22 16 00-0002	Ī	EA	contractor for Fee is \$1.00. to the actual I Reimbursable each one sep identify the Re various permi	eligible co Insert the Reimbursa Fee). If the arately an eimbursab ts, extende	ests. appr ble f nere d add le Fe ed w	sable Fees will The base cost opriate quantit Fee (e.g. quant are multiple Re d a comment ir ee (e.g. sidewa arrantee, expe shall be submi	of the Rei y to adjust ity of 125 = eimbursabl n the "note lk closure, dited shipp	mbursable the base cost = \$125.00 e Fees, list " block to road cut, bing costs,	\$18,421.21
					Qty		Unit Price	Factor	Total	
				Installation	13340	Χ	\$1.00 X	1.3809	\$18,421.21	
		Contractor N	lotes:	Payment and	Performa	nce I	Bond			
90	01 71 23 16-0006	ŀ	⊣R				Of Measure Is odman, chainn			\$4,512.51
					Qty		Unit Price	Factor	Total	
				Installation	20	Х	\$163.39 X	1.3809	\$4,512.51	
		Contractor N	Notes:	Shade structu column layou		swa	le layouts, CMI	U Wall layo	out, CMU	

Marphite   Marphite		CSI Number	Mod	UOM	Description						LineTotal
Section   Parameter   Parame	Gen	eral Requirements									
Installation   2	91	01 74 19 00-0014		EA	dumpster, ren	tal cost, p					\$1,770.09
Page						Qty		Unit Price	Factor	Total	
Months					Installation	2	Χ	\$640.92 X	1.3809	\$1,770.09	
Second   S	92	01 56 26 00-0143		LF	. ,	High Cha	in Lir	nk Fence Pane	ls (Portable	e), Up To 6	\$3,065.18
93    01 56 26 00-0143   0076   MOD   For >250 To 500, Deduct   (\$304.49)						Qty		Unit Price	Factor	Total	
Part					Installation	490	Χ	\$4.53 X	1.3809	\$3,065.18	
Installation	93	01 56 26 00-0143	0076	MOD	For >250 To 5	00, Dedu	ıct				(\$304.49)
94						Qty		Unit Price	Factor	Total	
Part					Installation	490	Χ	(\$0.45) X	1.3809	(\$304.49)	
Installation	94	01 56 26 00-0143	0079	MOD	For Shade Clo	oth, Add					\$1,725.43
Page						Qty		Unit Price	Factor	Total	
Placement and removal.   Placement and remove and removal.   Placement and remove and removal.   Placement and removal.   Placement and remove and remove and removal.					Installation	490	Χ	\$2.55 X	1.3809	\$1,725.43	
Installation   196   X   \$2.65 X   1.3809   \$717.24	95	01 56 26 00-0158		BAG				e Panels (Porta	able) Sandl	oagIncludes	\$717.24
Contractor Notes: 490/10 panels = 49x4 sandbags per panel						Qty		Unit Price	Factor	Total	
Second Part					Installation	196	Χ	\$2.65 X	1.3809	\$717.24	
Construction, 4 Úprights Set In Earth 2' Deep, With Double Rail   Qty			Contrac	ctor Notes:	490'/10' panel	s = 49x4	sand	bags per pane	I		
Installation   38	96	01 56 39 00-0003		EA							\$4,785.12
Contractor Notes: 9 existing trees and 29 relocated trees						Qty		Unit Price	Factor	Total	
Section   Sect					Installation	38	Χ	\$91.19 X	1.3809	\$4,785.12	
Second Pressure   Second Pre			Contrac	ctor Notes:	9 existing tree	s and 29	reloc	ated trees			
Installation   490   X   \$1.20 X   1.3809   \$811.97	97	31 25 14 26-0003		LF	2' High Silt Fe	nce with	Stake	es at 4' On Cen	iter		\$811.97
Second						Qty		Unit Price	Factor	Total	
Note   Processing Part   Part   Processing Pactor   Pac					Installation	490	Χ	\$1.20 X	1.3809	\$811.97	
Installation   2   X   \$33.56   X   1.3809   \$92.69	98	31 25 14 26-0031		EA	2' x 3' x 3' Inle	t Protecti	on Se	ediment Bag			\$92.69
Subtotal for General Requirements: \$35,596.95						Qty		Unit Price	Factor	Total	
100   22 11 19 00-0353   EA					Installation	2	Χ	\$33.56 X	1.3809	\$92.69	
99 03 31 13 00-0110							Su	btotal for Ge	eneral Re	quirements:	\$35,596.95
Qty Unit Price Factor Total Installation 1 X \$11.25 X 1.3809 \$15.54  Contractor Notes: Backflow Preventer pad  100 22 11 19 00-0353  EA 1" Threaded Reduced Pressure Zone Assembly With Quarter Turn Shut-offs And Strainer (Watts 009 QT-S series)  Qty Unit Price Factor Total	Irrig	ation									
Installation 1 X \$11.25 X 1.3809 \$15.54  Contractor Notes: Backflow Preventer pad  100 22 11 19 00-0353  EA 1" Threaded Reduced Pressure Zone Assembly With Quarter Turn \$776.38  Shut-offs And Strainer (Watts 009 QT-S series)  Qty Unit Price Factor Total	99	03 31 13 00-0110		SF	4" Equipment	Pad With	Reb	ar			\$15.54
Contractor Notes: Backflow Preventer pad  100 22 11 19 00-0353  EA 1" Threaded Reduced Pressure Zone Assembly With Quarter Turn \$776.38  Shut-offs And Strainer (Watts 009 QT-S series)  Qty Unit Price Factor Total						Qty		Unit Price	Factor	Total	
100 22 11 19 00-0353 EA 1" Threaded Reduced Pressure Zone Assembly With Quarter Turn Shut-offs And Strainer (Watts 009 QT-S series)  Qty Unit Price Factor Total								\$11.25 X	1.3809	\$15.54	
Shut-offs And Strainer (Watts 009 QT-S series)  Qty Unit Price Factor Total			Contrac	ctor Notes:	Backflow Prev	enter pa	d				
·	100	22 11 19 00-0353		EA						,	\$776.38
Installation 1 X \$562.23 X 1.3809 \$776.38						Qty		Unit Price	Factor	Total	_
					Installation	1	Χ	\$562.23 X	1.3809	\$776.38	

LineTotal					Description	UOM	Mod	CSI Number	
								ation	Irriga
\$709.23				ed Enclosure:	10-1/2" W x 24 Preventer Cag H x 25-1/2" LU	EA		22 11 19 00-0527	101
	Total	Factor	Unit Price	Qty					
	\$709.23	1.3809	\$513.60 X	1 X	Installation				
			losure	enter cage en	Backflow Prev	tor Notes:	Contrac		
\$135.23	4P)	ainbird 180	nkler Head (Ra	ht, Spray Sp	4" Pop-Up Hei	EA		32 84 23 00-0004	102
	Total	Factor	Unit Price	Qty					
	\$135.23	1.3809	\$13.99 X	7 X	Installation				
\$287.23	12P)	Rainbird 18	rinkler Head (F	ight, Spray S	12" Pop-Up He	EA		32 84 23 00-0006	103
	Total	Factor	Unit Price	Qty					
	\$287.23	1.3809	\$20.80 X	10 X	Installation				
\$2,419.23	T (Rainbird	en, 1/2" NP	oler With Scree	ensating Bul	Pressure Com 1400)	EA		32 84 23 00-0017	104
	Total	Factor	Unit Price	Qty					
	\$2,419.23	1.3809	\$14.36 X	122 X	Installation				
\$231.70				With Check	4" Pop-Up Heig Sprinkler Head (Rainbird 5004	EA		32 84 23 00-0028	105
	Total	Factor	Unit Price	Qty					
	\$231.70	1.3809	\$23.97 X	7 X	Installation				
\$3,238.27				With Check	6" Pop-Up Heig Sprinkler Head (Rainbird 5006	EA		32 84 23 00-0029	106
	Total	Factor	Unit Price	Qty					
	\$3,238.27	1.3809	\$32.57 X	72 X	Installation				
\$522.67				r Head With	12" Pop-Up He Rotary Sprinkle (Rainbird 5012	EA		32 84 23 00-0030	107
	Total	Factor	Unit Price	Qty					
	\$522.67	1.3809	\$37.85 X	10 X	Installation				
\$1,159.13	trol Irrigation	temote Cor	stic, Electric R		1-1/2", 0.25 To Valve (Rainbirg	EA		32 84 23 00-0053	108
	Total	Factor	Unit Price	Qty					
	\$1,159.13	1.3809	\$139.90 X	6 X	Installation				
\$145.44	Box With Lid	ation Valve	ctangular Irriga		21.8" x 16.6" x (Rainbird® VB	EA		32 84 23 00-0099	109
	Total	Factor	Unit Price	Qty					
	\$145.44	1.3809	\$105.32 X	1 X	Installation				
\$443.08	lar Irrigation	ount, Modu			8-Station, Four Controller (Rai	EA		32 84 23 00-0160	110
	Total	Factor	Unit Price	Qty					
	\$443.08	1.3809	\$320.86 X	1 X	Installation				
\$781.33				ollers (Rainbi	Powder Coated Irrigation Contro concrete found	EA		32 84 23 00-0173	111
	Total	Factor	Unit Price	Qty					
	\$781.33	1.3809	\$565.81 X	1 X	Installation				

	CSI Number	Mod UOM	Description	LineTotal
Irriga	ation			
112	32 84 23 00-0190	EA	Wireless Rain Sensor And Controller Interface For Irrigation Controllers (Rainbird WR2RC)	\$149.33
			Qty Unit Price Factor Total	
			Installation 1 X \$108.14 X 1.3809 \$149.33	
113	32 84 23 00-0372	LF	3/4" Class 200 Polyvinyl Chloride (PVC) Socketweld Pipe With Fittings	\$2,071.68
			Qty Unit Price Factor Total	
			Installation 1128 X \$1.33 X 1.3809 \$2,071.68	
114	32 84 23 00-0372	0415 MOD	For >1,000, Deduct	(\$109.04)
			Qty Unit Price Factor Total	
			Installation 1128 X (\$0.07) X 1.3809 (\$109.04)	
115	32 84 23 00-0373	LF	1" Class 200 Polyvinyl Chloride (PVC) Socketweld Pipe With Fittings	\$488.44
			Qty Unit Price Factor Total	
			Installation 217 X \$1.63 X 1.3809 \$488.44	
116	32 84 23 00-0374	LF	1-1/2" Class 200 Polyvinyl Chloride (PVC) Socketweld Pipe With Fittings	\$1,081.52
			Qty Unit Price Factor Total	
			Installation 334.7 X \$2.34 X 1.3809 \$1,081.52	
		Contractor Notes:	1 1/4" req	
117	32 84 23 00-0375	LF	2" Class 200 Polyvinyl Chloride (PVC) Socketweld Pipe With Fittings	\$606.49
			Qty Unit Price Factor Total	
			Installation 144 X \$3.05 X 1.3809 \$606.49	
118	32 84 23 00-0377	LF	1/2" Schedule 40 Polyvinyl Chloride (PVC) Pipe With Fittings	\$196.92
			Qty Unit Price Factor Total	
			Installation 124 X \$1.15 X 1.3809 \$196.92	
119	32 84 23 00-0380	LF	1-1/2" Schedule 40 Polyvinyl Chloride (PVC) Pipe With Fittings	\$5,542.59
			Qty Unit Price Factor Total	
			Installation 1625 X \$2.47 X 1.3809 \$5,542.59	
		Contractor Notes:	Main Line	
120	33 11 13 23-0129	LF	4" Schedule 80 Polyvinyl Chloride (PVC) Pipe	\$441.60
			Qty Unit Price Factor Total	
			Installation 56.4 X \$5.67 X 1.3809 \$441.60	
121	32 84 23 00-0416	CLF	2-Conductor, 18 AWG, Irrigation Control Wire, Buried In Trench	\$220.53
			Qty Unit Price Factor Total	
			Installation 5 X \$31.94 X 1.3809 \$220.53	
			Subtotal for Irrigation:	\$21,554.49
Land	dscaping			
122	01 74 19 00-0036	CYM	Hauling On Paved Roads, Miles Over Initial 15 Miles	\$622.03
			Qty Unit Price Factor Total	
			Installation 1155 X \$0.39 X 1.3809 \$622.03	
		Contractor Notes:	77 CY Top Soil x 15 add miles = 1155 CYM (St Augustine+P. Peanut)	

	CSI Number	Mod UOM	Description	l					LineTotal
Land	dscaping								
123	32 91 13 16-0002	CY	Pine Bark Nu	gget Mulcl	h				\$372.57
				Qty		Unit Price	Factor	Total	
			Installation	5	Χ	\$53.96 X	1.3809	\$372.57	
124	32 91 13 26-0002	SF	loosening sub	grade, rer	movii	Up To 8" Deeping stones, stick	ks, roots, r		\$371.35
				Qty		Unit Price	Factor	Total	
			Installation	672.3	Χ	\$0.40 X	1.3809	\$371.35	
		Contractor Note	s: or Perenial Pe	eanut					
125	32 91 19 13-0013	SY	Furnish And F	Place Impo	orted	Screened Top	soil, 4" De	ер	\$4,161.26
				Qty		Unit Price	Factor	Total	
			Installation	688	Χ	\$4.38 X	1.3809	\$4,161.26	
		Contractor Note	s: St Augustine+	-P. Peanu	t				
126	32 91 19 16-0003	MSF	>5,000 To 20,	,000 SF S	carify	/ Up To 8" Sub	soil With N		\$142.16
				Qty		Unit Price	Factor	Total	
			Installation	5.523	Х	\$18.64 X	1.3809	\$142.16	
127	32 92 23 00-0040	MSF	>4,000 To 8,0	000 SF, St	. Aug	gustine Sod, In:	stalled On	Level Ground	\$3,936.45
				Qty		Unit Price	Factor	Total	
			Installation	5.523	Χ	\$516.14 X	1.3809	\$3,936.45	
128	32 93 13 00-0095	EA	1 Gallon Lirio	oe 'Evergr	een	Giant'			\$1,922.21
				Qty		Unit Price	Factor	Total	
			Installation	435	Χ	\$3.20 X	1.3809	\$1,922.21	
		Contractor Note	s: Perennial pea	nut					
129	32 93 13 00-0102	EA	3 Gallon Neph	3 Gallon Nephrolepis - Swordfern/Boston Fern					\$393.68
				Qty		Unit Price	Factor	Total	
			Installation	39	Χ	\$7.31 X	1.3809	\$393.68	
130	32 93 33 00-0232	EA	7 Gallon Myrc	ianthes fr	agraı	ns - Simpson's	Stopper		\$302.80
				Qty		Unit Price	Factor	Total	
			Installation	8	Χ	\$27.41 X	1.3809	\$302.80	
		Contractor Note	s: Twinberry req	1					
131	32 93 33 00-0233	EA	15 Gallon Myr	rcianthes f	fragra	ans - Simpson'	s Stopper		\$1,514.02
				Qty		Unit Price	Factor	Total	
			Installation	20	Χ	\$54.82 X	1.3809	\$1,514.02	
		Contractor Note	s: 15gal var 6-12	2' tall					
132	32 93 33 00-0292	EA	3 Gallon Psyc	hotria ligu	ıstrifo	olia - Dwarf Wil	d Coffee		\$1,931.08
				Qty		Unit Price	Factor	Total	
			Installation	153	Χ	\$9.14 X	1.3809	\$1,931.08	
133	32 93 43 00-0059	EA	10 To 12' Bulr	nesia arbo	rea -	- Bulnesia			\$3,898.67
				Qty		Unit Price	Factor	Total	
			Installation	8	Χ	\$352.91 X	1.3809	\$3,898.67	
134	32 93 43 00-0183	EA	11' To 12' Cor	ncarpus e	rectu	s sericeus - Sil	ver Buttor	wood	\$1,514.09
				Qty		Unit Price	Factor	Total	
			Installation	5	Χ	\$219.29 X	1.3809	\$1,514.09	
		Contractor Note	s: 12' h req						

	CSI Number	Mod	UOM	Description						LineTotal
Lanc	dscaping									
135	32 93 43 00-0191		EA	10' To 12' Cord	dia sebe	stena	- Geiger Tree			\$1,135.56
					Qty		Unit Price	Factor	Total	
				Installation	3	Χ	\$274.11 X	1.3809	\$1,135.56	
136	32 93 43 00-0582		EA	13' To 14' Que	rcus virg	jinian	a - Live Oak			\$1,766.45
					Qty		Unit Price	Factor	Total	
				Installation	5	Χ	\$255.84 X	1.3809	\$1,766.45	
137	32 93 43 00-0584		EA	17' To 18' Que	rcus virg	ginian	a - Live Oak			\$2,725.40
					Qty		Unit Price	Factor	Total	
				Installation	6	Χ	\$328.94 X	1.3809	\$2,725.40	
		Contrac	tor Notes:	20-24' req						
138	32 93 43 00-0960		EA	10 Gallon Dyp	sis lutes	cens	- Areca Palm			\$15,824.38
					Qty		Unit Price	Factor	Total	
				Installation	209	Χ	\$54.83 X	1.3809	\$15,824.38	
		Contrac	tor Notes:	Clusia Guttifer	а					
139	32 93 53 00-0022		EA	12' Balled And	Burlapp	ed Tr	ee Planting			\$7,707.41
					Qty		Unit Price	Factor	Total	
				Installation	36	Χ	\$155.04 X	1.3809	\$7,707.41	
		Contrac	tor Notes:	Verawood 8+S Stopper 20	SilverBot	tonwo	ood 5+Orange (	Geigger 3	Simpson's	
140	32 93 53 00-0023		EA	14' Balled And	Burlapp	ed Tr	ee Planting			\$1,226.10
					Qty		Unit Price	Factor	Total	
				Installation	5	Χ	\$177.58 X	1.3809	\$1,226.10	
		Contrac	tor Notes:	Live Oak						
141	32 93 53 00-0026		EA	20' Balled And	Burlapp	ed Tr	ee Planting			\$1,646.97
					Qty		Unit Price	Factor	Total	
				Installation	4	Χ	\$298.17 X	1.3809	\$1,646.97	
		Contrac	tor Notes:	Live oak						
142	32 93 53 00-0036		EA	3 Gallon Conta	ainer Shr	ub Pl	anting			\$5,504.18
					Qty		Unit Price	Factor	Total	
				Installation	401	Χ	\$9.94 X	1.3809	\$5,504.18	
		Contrac	tor Notes:	209 Clusia+39	Boston	Fern-	+153 Bahama (	Coffee		
143	32 93 53 00-0036	0260	MOD	For >100, Ded	uct					(\$1,650.15)
					Qty		Unit Price	Factor	Total	
				Installation	401	Χ	(\$2.98) X	1.3809	(\$1,650.15)	
144	32 93 53 00-0039		EA	7 Gallon Conta	ainer Shr	ub Pl	anting			\$248.89
					Qty		Unit Price	Factor	Total	
				Installation	8	Χ	\$22.53 X	1.3809	\$248.89	
		Contrac	tor Notes:	Twinberry						
145	32 93 53 00-0064		EA	1 Gallon Conta	ainer Gro	oundo	over And Flow	er Planting	l	\$3,183.67
					Qty		Unit Price	Factor	Total	
				Installation	435	Χ	\$5.30 X	1.3809	\$3,183.66	
		Contrac	tor Notes:	Perennial Pea	nut					

	CSI Number	Mod	UOM	Description						LineTotal
Lan	dscaping									
146	32 93 53 00-0064	0264	MOD	For >100, Dec	luct					(\$955.10)
					Qty		Unit Price	Factor	Total	
				Installation	435	Χ	(\$1.59) X	1.3809	(\$955.10)	
147	32 94 49 00-0010		EA	Tree Guying 8 Rope	" And Up	Calip	per, 8" Anchors	And Poly	propylene Flat	\$12,305.89
					Qty		Unit Price	Factor	Total	
				Installation	78	Χ	\$114.25 X	1.3809	\$12,305.89	
148	32 94 49 00-0020		EA	Stake Out Tre	es Or Shr	ubs				\$1,412.25
					Qty		Unit Price	Factor	Total	
				Installation	487	Χ	\$2.10 X	1.3809	\$1,412.25	
149	32 96 43 00-0006		EA	>48" To 60" R	oot Ball, I	Move	Trees On Site	!		\$28,613.67
					Qty		Unit Price	Factor	Total	
				Installation	33	Χ	\$627.91 X	1.3809	\$28,613.67	
		Contrac	ctor Notes:	Palm relocation	on				. ,	
150	32 91 13 16-0000		LS	Silva Cell Sys	tem					\$12,849.16
	02 01 10 10 0000		NPP		Qty		Unit Price	Factor	Total	ψ.Ξ,σ.σσ
			Tasks	Installation	1	X	\$10,960.64 X		\$12,849.16	
		Contrac	ctor Notes:	Silva Cell Roc					• •	
						φ.σ,				\$444 GOZ 40
							Subto	otal for L	andscaping:	\$114,627.10 
Mas	onry									
151	04 05 16 26-0009		SF		Grout Concrete Block Cores- 8" Block Concrete Fill Block Solid (0.258 CF/SF)				\$3,788.30	
					Qty		Unit Price	Factor	Total	
				Installation	Qty 723.84	Х	Unit Price \$3.79 X		Total \$3,788.30	
152	04 05 16 26-0011		SF		723.84 e Block C			1.3809	\$3,788.30	\$773.69
152	04 05 16 26-0011		SF	Grout Concret	723.84 e Block C		\$3.79 X	1.3809	\$3,788.30	\$773.69
152	04 05 16 26-0011		SF	Grout Concret	723.84 te Block C		\$3.79 X - 12" Block Col	1.3809 ncrete Fill Factor	\$3,788.30 Block Solid	\$773.69
152 153	04 05 16 26-0011 04 05 19 26-0007		SF	Grout Concret (0.422 CF/SF) Installation	723.84 re Block C Qty 101.5	ores	\$3.79 X - 12" Block Col	1.3809 ncrete Fill Factor 1.3809	\$3,788.30 Block Solid Total \$773.69	·
			-	Grout Concret (0.422 CF/SF) Installation	723.84 re Block C Qty 101.5	ores	\$3.79 X - 12" Block Cor Unit Price \$5.52 X	1.3809 ncrete Fill Factor 1.3809	\$3,788.30 Block Solid Total \$773.69	·
			-	Grout Concret (0.422 CF/SF) Installation	723.84 re Block C Qty 101.5	X al Pla	\$3.79 X - 12" Block Cor Unit Price \$5.52 X Iced, Steel Mas	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor	\$3,788.30  Block Solid  Total  \$773.69  forcement Bar	·
		Contrac	LF	Grout Concret (0.422 CF/SF) Installation #4, Grade 50,	723.84 Te Block Co  Qty  101.5  Horizonta	X al Pla	\$3.79 X - 12" Block Cor Unit Price \$5.52 X Iced, Steel Mas	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor	\$3,788.30  Block Solid  Total \$773.69  forcement Bar Total	·
		Contrac	LF	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap	723.84 Te Block Control Qty 101.5 Horizonta Qty 264	X al Pla	\$3.79 X - 12" Block Cor Unit Price \$5.52 X Iced, Steel Mas	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10	\$328.10
153	04 05 19 26-0007	Contrac	LF ctor Notes:	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap	723.84 The Block Control of the Property of th	X al Pla	\$3.79 X - 12" Block Cor  Unit Price \$5.52 X ced, Steel Mas Unit Price \$0.90 X	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10	\$773.69 \$328.10 \$786.28
153	04 05 19 26-0007	Contrac	LF ctor Notes:	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap	723.84 Te Block Control Qty 101.5 Horizonta Qty 264	X al Pla	\$3.79 X - 12" Block Con Unit Price \$5.52 X aced, Steel Mas Unit Price \$0.90 X d, Steel Masor	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 rry Reinfor Factor	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10	\$328.10
153	04 05 19 26-0007		LF ctor Notes: LF	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50,	723.84 re Block Co  Qty 101.5  Horizonta Qty 264  Vertical F Qty 390	X  X  X  X  Place	\$3.79 X - 12" Block Cor  Unit Price \$5.52 X ced, Steel Mas Unit Price \$0.90 X  d, Steel Masor Unit Price \$1.46 X	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 rry Reinfor Factor	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10	\$328.10
153	04 05 19 26-0007 04 05 19 26-0016		LF  tor Notes:  LF  ctor Notes:	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50, Installation Wall Vertical	723.84 Te Block Control  Qty 101.5  Horizonta  Qty 264  Vertical F  Qty 390  Reinforce	X X X X X X X X Mention	\$3.79 X - 12" Block Con Unit Price \$5.52 X aced, Steel Mas Unit Price \$0.90 X d, Steel Masor Unit Price \$1.46 X	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 nry Reinfor Factor 1.3809	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10	\$328.10 \$786.28
153	04 05 19 26-0007		LF ctor Notes: LF	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50, Installation Wall Vertical	723.84 Te Block Concentration of the process of the	X X X X X X X X Mention	\$3.79 X - 12" Block Con Unit Price \$5.52 X ICCED, Steel Masor Unit Price \$0.90 X   d, Steel Masor Unit Price \$1.46 X t Up Concrete B	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 rry Reinfor Factor 1.3809	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10  cement Bar  Total \$786.28	\$328.10
153	04 05 19 26-0007 04 05 19 26-0016		LF  tor Notes:  LF  ctor Notes:	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50, Installation Wall Vertical 8" x 16" x 8", I	723.84  The Block Control of the Property of t	X X X Place X ment	\$3.79 X - 12" Block Con Unit Price \$5.52 X Inced, Steel Mass Unit Price \$0.90 X  Inced, Steel Masor Unit Price \$1.46 X Inced Up Concrete B Unit Price	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 rry Reinfor 1.3809 slock Factor	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10  rement Bar  Total \$786.28	\$328.10 \$786.28
153	04 05 19 26-0007 04 05 19 26-0016 04 22 23 13-0006		LF  LF  ctor Notes:  SF	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50, Installation Wall Vertical 8" x 16" x 8", I	723.84 Te Block Color Qty 101.5 Horizonta Qty 264  Vertical F Qty 390 Reinforce Regular, E Qty 723.84	X X X Place X ment	\$3.79 X - 12" Block Con Unit Price \$5.52 X ICCED, Steel Masor Unit Price \$0.90 X  d, Steel Masor Unit Price \$1.46 X f Up Concrete B Unit Price \$7.40 X	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 nry Reinfor Factor 1.3809	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10  cement Bar  Total \$786.28	\$328.10 \$786.28 \$7,396.67
153	04 05 19 26-0007 04 05 19 26-0016		LF  tor Notes:  LF  ctor Notes:	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50, Installation Wall Vertical 8" x 16" x 8", I	723.84 Te Block Color Qty 101.5 Horizonta Qty 264  Vertical F Qty 390 Reinforce Regular, E Qty 723.84  Regular,	X X X Place X ment	\$3.79 X - 12" Block Cor Unit Price \$5.52 X ICCED, Steel Masor Unit Price \$0.90 X  ICCED MASOR Unit Price \$1.46 X ICCED MASOR Unit Price \$1.46 X ICCED MASOR Unit Price \$1.46 X ICCED MASOR Unit Price \$1.46 X ICCED MASOR Unit Price \$1.40 X ICCED Concrete	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 rry Reinfor Factor 1.3809 Block Factor 1.3809 Block	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10  cement Bar  Total \$786.28	\$328.10 \$786.28
153	04 05 19 26-0007 04 05 19 26-0016 04 22 23 13-0006		LF  LF  ctor Notes:  SF	Grout Concret (0.422 CF/SF) Installation #4, Grade 50, Installation Wall Cap #5, Grade 50, Installation Wall Vertical 8" x 16" x 8", I	723.84 Te Block Color Qty 101.5 Horizonta Qty 264  Vertical F Qty 390 Reinforce Regular, E Qty 723.84	X X X Place X ment	\$3.79 X - 12" Block Con Unit Price \$5.52 X ICCED, Steel Masor Unit Price \$0.90 X  d, Steel Masor Unit Price \$1.46 X f Up Concrete B Unit Price \$7.40 X	1.3809 ncrete Fill Factor 1.3809 sonry Rein Factor 1.3809 nry Reinfor 1.3809 slock Factor 1.3809 Block Factor	\$3,788.30  Block Solid  Total \$773.69  forcement Bar  Total \$328.10  rement Bar  Total \$786.28	\$328.10 \$786.28 \$7,396.67

	CSI Number	Mod	UOM	Description						LineTotal
Mas	onry									
157	04 22 23 13-0008	0036	MOD	For <10, Smal	l Area Re	eplace	ements (Individ	dual Areas	, Add	\$0.00
					Qty		Unit Price	Factor	Total	
				Installation	0	Χ	\$11.19 X	1.3809	\$0.00	
158	04 72 00 00-0012		SF	2" Thick Preca	st Concr	ete C	oping			\$3,213.08
					Qty		Unit Price	Factor	Total	
				Installation	84	Χ	\$27.70 X	1.3809	\$3,213.08	
		Contractor	r Notes:	2' x 2'						
								Subtotal f	or Masonry:	\$17,628.86
Play	ground Assembly									
	-		HR	CarpontarEar	taaka nat	inglu	idad in the Cor	actruction 7	Tack Catalog®	\$20,002,64
159	01 22 20 00-0006		пк	CarpenterFor and as directe				istruction	ask Catalog®	\$30,092.64
					Qty		Unit Price	Factor	Total	
				Installation	565	Χ	\$38.57 X	1.3809	\$30,092.64	
		Contractor	r Notes:	Assembly and						
				furnishings: Cl Picnic Benche				orn Stalks, i	Play Mounds,	
				T TOTAL BOTTOTIO	o, 11doi1			0.4940110	d Accombby	\$30,092.64
						- Su	וטנטנמו וטו דו	aygroun	d Assembly:	\$30,092.04 
Plun	mbing									
160	01 45 23 00-0227		EA	Staff Engineer only as directed						\$662.83
				investigational						
				minimum.						
					Qty		Unit Price	Factor	Total	
				Installation	12	X	\$40.00 X	1.3809	\$662.83	
		Contractor	r Notes:	Backflow prev	enter cer	tificat	tions (Irrigation	& Plumbir	ng)	
161	02 41 19 13-0063		EA	Saw Cut Minin						\$667.58
				charge is less This task shou						
				this section.						
					Qty		Unit Price	Factor	Total	
				Installation	1	X	\$483.44 X	1.3809	\$667.58	
		Contractor	r Notes:	Water meter ti	e-in					
162	03 31 13 00-0111		SF	6" Equipment	Pad With	Reb	ar			\$232.82
					Qty		Unit Price	Factor	Total	
				Installation	12	Χ	\$14.05 X	1.3809	\$232.82	
		Contractor	r Notes:	Backflow Prev	enter pa	d				
163	22 11 16 00-0824		LF	1/2" Inside Dia						\$584.40
				all hangers an are complete a						
					Qty		Unit Price	Factor	Total	
				Installation	40	Х	\$10.58 X	1.3809	\$584.40	
		Contractor	r Notes:	Water fountair	)					
164	22 11 16 00-0844		LF	2" Schedule 8	0 Chlorin	ated	Polyvinyl Chlo	ride (CPVC	c) Pressure	\$111.58
				Pipe				`		
					Qty		Unit Price	Factor	Total	
				Installation	10	Χ	\$8.08 X	1.3809	\$111.58	
		Contractor	r Notes:	Water fountair	drain lin	ne				

	CSI Number	Mod	UOM	Description						LineTotal
Plun	nbing									
165	22 11 19 00-0261		EA				Valve Assembl s 007 QT-S or		rter Turn	\$1,139.89
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$825.47 X	1.3809	\$1,139.89	
		Contract	tor Notes:	Backflow Prev	venter					
166	22 11 19 00-0528		EA		ged Enclo		L Internal Dime s, External Dim			\$803.71
					Qty		Unit Price	Factor	Total	
				Installation	1	Χ	\$582.02 X	1.3809	\$803.71	
		Contract	tor Notes:	Backflow Prev	enter cag	ge en	closure			
167	22 47 19 00-0004		EA	Tri-level Outde Filler And Two LK4430BF1)			\$264.84			
		Excl			Qty		Unit Price	Factor	Total	
		Material		Installation	1	Χ	\$191.79 X	1.3809	\$264.84	
		Contract	tor Notes:	Installation on	ly. Exclud	des v	vater fountain			
168	31 05 16 00-0008		CY	#57 Stone Ag	gregate F	ill (#4	I To 1")			\$153.28
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$55.50 X	1.3809	\$153.28	
		Contract	tor Notes:	Water fountail	Vater fountain drain pit					
169	31 05 16 00-0008	0050	MOD	For Up To 10,	Add					\$44.63
					Qty		Unit Price	Factor	Total	*******
				Installation	2	Х	\$16.16 X		\$44.63	
170	31 05 16 00-0030		CY	Aggregate Pla	cementIn	clude	es Spreading, (	Grading, Co	ompaction	\$52.58
					Qty		Unit Price	Factor	Total	
				Installation	2	Х	\$19.04 X	1.3809	\$52.58	
		Contract	tor Notes:	Water fountain	n drain pit					
171	31 23 16 13-0005		CY	Over 12" Wide Rock	e, Excava	tion f	or Trenching b	y Machine	in Loose	\$17.40
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$6.30 X	1.3809	\$17.40	
		Contract	tor Notes:	Water fountain	n deep dra	ain p	it			
172	31 23 16 13-0005	0054	MOD	For Up To 20,	Add					\$13.92
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$5.04 X	1.3809	\$13.92	
173	31 23 16 13-0007		CY				y Hand In Soill ng sides and b			\$109.75
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$39.74 X	1.3809	\$109.75	
		Contract	tor Notes:	Water fountain	n drain lin	e exc	cavation water	connection		
174	31 23 16 13-0011		CY	Backfilling or I Stockpiled Ma	Placing Suterials by	ubba: Han	se for Trenche	s with Impo	rted or	\$30.49
					Qty		Unit Price	Factor	Total	
				Installation	2	Х	\$11.04 X	1.3809	\$30.49	
		Contract	tor Notes:	Water fountain	n drain lin	0 0V	ravation water	connection		

	CSI Number	Mod	UOM	Description	1					LineTota
Plun	nbing									
175	31 32 19 16-0006		SY	6.0 Oz/SY, 7	Mil, 160 I	_B G	rab Tensile N	lonwoven F	Polypropylene	\$5.58
				Geotextile Fa	bric (Carth	age	Mills FX-60H			
					Qty		Unit Price	Factor	Total	
				Installation		Х	\$1.01 >	( 1.3809	\$5.58	
		Contract	or Notes:	Water founta	in drain pit					
176	31 32 19 16-0006	0081	MOD	For Up To 50	, Add				,	\$1.16
					Qty		Unit Price	Factor	Total	
				Installation	4	Х	\$0.21 >	( 1.3809	\$1.16	
							8	Subtotal f	or Plumbing:	\$4,896.44
Rub	ber Surface									
177	32 18 16 13-0037		SF	5' Critical Fal Surfacing (Pl				Rubber Pl	ayground	\$73,556.33
					Qty		Unit Price	Factor	Total	
				Installation	3945.7	Χ	\$13.50 >	( 1.3809	\$73,556.33	
							Subtot	al for Rub	ber Surface:	\$73,556.33
Sha	de Structure									
178	01 45 23 00-0226		EA	FloridaProfes	rofessional Engineer Registered in the State of oridaProfessional Engineering Services are to be used only as					
				directed by the services and	not for AE		gn services. 2	2 hour mini		
					Qty	.,	Unit Price	Factor	Total	
		0		Installation	40	X	·	( 1.3809	\$4,142.70	
		Contract	or Notes:	Shade Struct drawings/win				a ana seal	ea snop	
179	11 68 16 00-0137		EA	30' Peak-Roo Height, 3 Pos		Sha	de Structure,	12' Maximu	ım Opening	\$127,320.25
					Qty		Unit Price	Factor	Total	
				Installation	3	Χ	\$30,733.64 >	( 1.3809	\$127,320.25	
		Contract	or Notes:	Shade Struct	ures: Sails					
180	11 68 16 00-0164		EA	14' x 14' Sing Opening Heig		rami	d Shade Stru	cture, 12' N	laximum	\$38,147.56
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$13,812.57 >	( 1.3809	\$38,147.56	
		Contract	or Notes:	Shade Struct	ure: Torna	do				
181	05 12 23 00-0051		LB	Column Base	Plates, >1	150 L	_B / Each, A3	6 Miscellan	eous Steel	\$2,687.23
					Qty		Unit Price	Factor	Total	
				Installation	973	Χ	\$2.00 >	1.3809	\$2,687.23	
		Contract	or Notes:	11 units Shad	des Structu	ıres				
182	05 12 23 00-0051	0001	MOD	For ASTM A2	242 Type 2	Higl	h Strength Ste	eel, Add		\$188.11
					Qty		Unit Price	Factor	Total	
				Installation	973	Х	\$0.14 >	( 1.3809	\$188.11	
							Subtota	I for Sha	de Structure:	\$172,485.85

	CSI Number	Mod	UOM	Description						LineTotal
Stee	I Fence									
183	32 31 13 13-0010		VLF	12" Diameter I	Hole, Aug	er B	y Machine Fen	ce Post H	ole In Soil	\$1,615.76
					Qty		Unit Price	Factor	Total	
				Installation	142	Χ	\$8.24 X	1.3809	\$1,615.76	
		Contrac	ctor Notes:	2' Deep x 71P	ost					
184	32 31 19 00-0035		LF	4' Steel Tube I 1/2" Square P		ertica	lls At >2-1/2" T	o 3" On C	enter With 2-	\$17,110.18
					Qty		Unit Price	Factor	Total	_
				Installation	321	Χ	\$38.60 X	1.3809	\$17,110.18	
185	32 31 19 00-0035	0122	MOD	For Verticals >	3" To 4"	On C	enter, Deduct			(\$1,338.67)
					Qty		Unit Price	Factor	Total	
				Installation	321	Χ	(\$3.02) X	1.3809	(\$1,338.67)	
186	32 31 19 00-0035	0125	MOD	For Solid Pick	ets, Add					\$3,568.31
					Qty		Unit Price	Factor	Total	
				Installation	321	Χ	\$8.05 X	1.3809	\$3,568.31	
187	32 31 19 00-0035	0127	MOD	For Third Rail,	Add					\$1,001.79
					Qty		Unit Price	Factor	Total	
				Installation	321	Χ	\$2.26 X	1.3809	\$1,001.79	
188	32 31 19 00-0035	0129	MOD	For Color, Add	1					\$669.34
					Qty		Unit Price	Factor	Total	
				Installation	321	Χ	\$1.51 X	1.3809	\$669.34	
189	32 31 19 00-0046		EA		' Wide x 4' High Steel Tube Swing Gate, Hardware And ssociated Trim				And	\$1,783.21
					Qty		Unit Price	Factor	Total	_
				Installation	2	Χ	\$645.67 X	1.3809	\$1,783.21	
190	32 31 19 00-0046	0125	MOD	For Solid Pick	ets, Add					\$396.07
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$143.41 X	1.3809	\$396.07	
191	32 31 19 00-0046	0127	MOD	For Third Rail,	Add					\$128.59
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$46.56 X	1.3809	\$128.59	
192	32 31 19 00-0046	0134	MOD	For Color, Add	i					\$85.73
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$31.04 X	1.3809	\$85.73	
193	32 31 19 00-0048		EA	6' Wide x 4' Hi Associated Tri		Tube	Swing Gate, F	Hardware .	And	\$2,145.37
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$776.80 X	1.3809	\$2,145.37	
194	32 31 19 00-0048	0125	MOD	For Solid Pick	ets, Add					\$476.11
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$172.39 X	1.3809	\$476.11	
195	32 31 19 00-0048	0127	MOD	For Third Rail,	Add					\$154.30
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$55.87 X	1.3809	\$154.30	

	CSI Number	Mod	UOM	Description						LineTotal
Stee	l Fence									
196	32 31 19 00-0048	0134	MOD	For Color, Add						\$102.88
					Qty		Unit Price	Factor	Total	
				Installation	2	Χ	\$37.25 X	1.3809	\$102.88	
197	32 31 19 00-0093		EA	4" Ball Cap						\$1,535.37
					Qty		Unit Price	Factor	Total	
				Installation	71	Χ	\$15.66 X	1.3809	\$1,535.37	
		Contracto	r Notes:	71 post						
							Sub	total for	Steel Fence:	\$29,434.34
								G	rand Total:	\$629,329.61

This work order proposal total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding of the line totals and sub-totals.

The Percent of NPP on this Proposal: 2.04