

# POLO PARK

## BASEBALL FIELD IMPROVEMENTS

### LEGEND

1. New benches
2. Existing drinking fountain
3. New 5' wide perimeter path
4. Existing 6' high picket fence
5. New chilled drinking fountains
6. New concrete path at entry
7. New bleachers
8. Picnic tables
9. New 16' - 20' high backstop (existing 14')
10. Clay to be extended out to new fence
11. New 8'-10' high fence (existing 4') and 8'-10' safety netting
12. New dugout
13. New dugout (replacing existing)
14. Relocated irrigation pump
15. (Not pictured) Trash and recycling receptacles added throughout park
16. (Not pictured) Entrance gate enhancements and signage

0 20 40ft

