Project: 1824 AQUA HOTEL

Plan Correction Report Matrix

Plan Correction Report Matrix
Date: 11.01.2019
Plan Address: 1530 Collins Avenue, Miami Beach, FL 33139
1st App. Date: 10/7/2019

	HPB Comments	Response	Reference SI
ironm	ental Review - not reviewed		
2 Dlan	n Review		*
Pian	HPB19-0353. 1530 Collins Avenue		
	First submittal: October 21, 2019		
	Comments issued: November 1, 2019		
	Final submittal (CAP & Paper): November 12, 2019		
	Notice to proceed issued: November 18, 2019		
	Agenda finalized & all fees paid by: November 20, 2019		
	Tentative HPB meeting agenda date: January 14, 2020		
	DEFICIENCIES IN ARCHITECTURAL PRESENTATION		
a	The renderings are not consistent with the elevation drawing:	Renderings have been updated	A-601, A-60
b	Provide existing and proposed interior elevation drawings of the lobb	Interior elevations of lobby area added	A-009a
0	Provide a detail drawing of the double railing system and explanation of design	Detail added. Proposed railing enhances the horizontal design of the historic building. A glass panel is added to the rear	
		of the horizontal bars for security reasons, to prevent potential climbing due to the ladder created by the horizontal bars	
d	Clarify the reason for the lift at the driveway	The ADA lift is required to provide accessibility from the drop off area since the vehicular ramp does not have the	A-032
		required slope and the ramp provided only allows accessibility from the sidewalk because is not accessible from the dro	p
		off area.	
Э	The rood deck heights are not consistent throughout the plans. Indicate roof deck heights in elevation and section drawings	Roof deck height revised and updated	A-100, A-10
f	The pantry/storage room and bar counter are not allowable height encroachment	Pantry/storage mislabeled, actually pool equiment room (mechanical area). Bar counter remove	A-105
	DESIGN/APPROPRIATENESS COMMENTS (Recommendations)		
3	Staff recommends that the fifth floor be further setback from the east face of the fourth floor and the east roof deck and railing be further	Further increasing setback from the east facade creates difficulties developing proper areas for the amenities at the root	
	setback back from the face of the fifth floor	deck and guestrooms depths. Our proposed design provides an equivalent setback than the recently built design for the	9
		1600 Collins Avenue. See graphic showing compared setbacks provided for both projects.	
)	Staff recommends swapping the location of the pool deck with the bar deck in order to lower the east deck height	Pool deck location allows to capture views of the ocean not possible from the south side. It is an important feature for	
		Hotel marketing and successful operations.	
;	Staff recommends providing a rendering of the courtyard area	Rendering provided	A-603
	URBAN FORESTRY GROUP REVIEW - NOT REVIEWED		
	PUBLIC WORKS - LUB REVIEW - NOT REVIEWED		
	TRANSPORTATION LUB DEL VEIN NOT DEL VEINE		
	TRANSPORTATION - LUB REVIEW - NOT REVIEWED		
	HPB ZONING REVIEW		
	ITTE ZUNING REVIEW Comments issued on November 1.		
	Provide a narrative responding to staff comments.	Provided	
2	Letter of intent is missing.	Included	
	Lot area shall be indicated in survey	See revised survey	
	Page A-003. Remove plumbing fixture calculations. Enlarge text on zoning setbacks	Plumbing fixture calculation eliminated. Texts enlarged.	A-003
	Revise grade elevation in zoning information. Survey indicates 6.9' NGVD along the front sidewalk	Revised	A-003
;	Revise rooms breakdown table and areas. Some inconsistencies are - Room with 320.25 sf is located at the 1 floor, not on second floor plan.	Revised	A-003
	Room with 303.25 sf at the ground level is only 1 unit, table show 2 units, etc		
,	Driveway front setback: In order to retain the existing driveway front setback, the Board shall find that the existing building and the addition	Please see attached graphic with calculated areas of driveway and setback	A-029
	complies with section 118-395(b)(2)d.2. for the replication and restoration of contributing buildings		
	Provide area of the existing driveway. Staff would recommend that the area of the new driveway would not exceed the existing of the driveway	Please see attached graphic with calculated areas of driveway and setback	A-029
)	As submitted, a variance from the minimum size for hotel units is required for the units within the new addition. The non-conforming units with	Variance Requested	
	the existing building are subject to the Board's approval based on section 118-395(b)(2)d.2		
)	Note that there is a parking requirement of 0.5 space per hotel unit	Parking Calculation added	A-003
1	Note that there are off-street loading requirements for the new hotel units. A waiver may be approved by the Board conditioned to the submitta	Waiver Requested	
	of a plan delineating on-street loading approved by the parking Department		
2	Height of restrooms at the roof shall be reduced to the minimum required by the Florida Building Code	Height adjusted	A-501
3	Bar counter is not an allowable height exception and shall be removed from root	Removed	A-105
1	Pantry/storage at the roof level is not allowed as a height exception and shall be removed from rool	Pantry/storage mislabeled, actually pool equiment room (mechanical area). Bar counter remove	A-105
5	Revise FAR calculations- bathrooms at the ground level shall be counted, all covered corridors around the courtyard shall count. Covered	Bathroom is been included in FAR. Covered corridors are part of the courtyard terrace area. Per definition of FAR	A-015 to A-
	courtyard shall count. Trash area can be removed from FAR	terraces are not included in FAR.	1 401
3	Indicate front setback to the elevated deck/seating area	Setback added added	A-101
7	Area of accessible roof deck above the main roof cannot exceed 50% of the area of the floor below. Provide area and calculations to satisfy	Calculation added	A-030
0	this requirement.	Coation shown Planters do not exceed 2! in heigh	A 502
<u>8</u> 9	Provide a section thru the planters at the roof level. Planters cannot exceed 3'-0" above the main roof	Section shown. Planters do not exceed 3' in heigh	A-502
<u>)</u>	Improve line weight on elevation drawings. Some features are missing	Improved Elevations revised	A-100 and A
1	Elevations of the roof decks are not consistent on pages A-100 and page A-105 Provide a section detail through the courtward	Elevations revised Enlargement provided	A-100 and A
2	Provide a section detail through the courtyard. The maximum width of the walkway on the east side cannot exceed 44". Clarify height of this walkway. Is this another ramp?	Enlargement provided Walkway proposed is 44". It is part of the accessible route from the sidewalk and it ramps up to the lobby elevation	A-504 A-101
_	The maximum width of the waitway on the east side earliest exceed 44. Clarify height of this waitway. Is this allother family?	Training proposed is 44. It is part of the accessible route from the shoewark and it rainips up to the housy elevation	7-101