

OTJ

DBR 23-0948 - REVISION 1 SUBMITTAL EXTERIOR IMPROVEMENTS

801 ARTHUR GODFREY RD. MIAMI BEACH, FL 33140

NOVEMBER 17TH, 2023

INDEX

0 COVER
1 SITE STUDY
2 SITE - APPROACH STUDY
3 SURVEY
4 ZONING & EXISTING GROUND PLAN
5 EXISTING ELEVATIONS & VIEWS
6 DEMO SITE PLAN
7 DEMO EXTERIOR ELEVATIONS
8 PROPOSED VIEW
9 PROPOSED VIEW
10 PROPOSED SITE PLAN
11 PROPOSED ENLARGE SITE PLAN
12 PROPOSED RCP
13 PHOTOMETRICS PLAN
14 PHOTOMETRICS EMERGENCY PLAN
15 PROPOSED ENLARGE PLANS
16 PROPOSED RENDER ELEVATION
17 PROPOSED EXTERIOR ELEVATIONS
18 PROPOSED PERSPECTIVE ELEVATIONS
19 PROPOSED ELEVATION PERSPECTIVE VIEW
20 PROPOSED ELEVATIONS
21 PROPOSED VIEW
22 PROPOSED BUILDING SECTION
23 PROPOSED SECTIONS DETAILS
24 PROPOSED PERSPECTIVE VIEW
25 PROPOSED PERSPECTIVE VIEW
26 PROPOSED PERSPECTIVE VIEW
27 LANDSCAPE EXISTING TREE DISPOSITION PLAN
28 LANDSCAPE PLANTING PLAN
29 LANDSCAPE PLANTING SPECS AND DETAILS
30 LANDSCAPE IRRIGATION LAYOUT PLAN
31 LANDSCAPE IRRIGATION SPEC & DETAILS

SCOPE

1. REMOVAL OF EXISTING RAMP:
 - CAREFULLY DEMOLISHING AND REMOVING THE EXISTING RAMP STRUCTURE.
2. RELOCATION OF STAIRS:
 - DESIGNING AND CONSTRUCTING NEW STAIRWAYS IN A MORE CONVENIENT AND ACCESSIBLE LOCATION.
3. INSTALLATION OF A NEW ADA LIFT:
 - CONDUCTING ANY NECESSARY MODIFICATIONS TO ACCOMMODATE THE LIFT, INCLUDING ELECTRICAL AND STRUCTURAL WORK.
4. UPGRADE OF FINISHES:
 - ENHANCING THE OVERALL APPEARANCE OF THE EXTERIOR BY UPGRADING FINISHES SUCH AS PAINTING, CLADDING, AND LANDSCAPING.
 - USING HIGH-QUALITY MATERIALS THAT ARE DURABLE AND REQUIRE MINIMAL MAINTENANCE.





801 ARTHUR GODFREY
S



TRUIST BANK
1



4141 APARTMENTS
2



GILLER BUILDING
3




SEPHARDIC CONGREGATION
4



SAND HOUSE
5



777 OFFICE BUILDING
6



TEMPLE BETH SHOLOM
7