NEW GL

NEW GLASS ELEVATOR ON COURTYARD NE CORNER - JUSTIFICATION

THE VILLA - CASA CASUARINA

1116 Ocean Drive Miami Beach, FL 33139



5

PROJECT TEAM

ARCHITECT OF RECORD



SKLARchitecture

2310 HOLLYWOOD BLY HOLLYWOOD, FL 3302 www.skiarchitect.com Office (954) 925-9292 Fax (954) 925-9292 AA 0002949 IS 000894 NCARS CERTIFIED

OWNER

VMSB LLC 1400 Breadway, 15th Floor, Ny, NY 645-467,1399 Owners Rip: Gesenberg Traurig, P.A. Affredo J. Grozzlicz 333.5.E. 2nd Avenue | Marris, FL 33131 T +1 305.579.0588 | F +1 305.961.5588 Ernel: GenzaliscA (Spatisoc.com

SCOPE OF WORK

NEW ELEVATOR AT NORTH INTERIOR CENTRAL COURTYARD:

Round Glass 3 story Elevator located on North East Corner of Courtyard

LEGAL DESCRIPTION

тна ексепяту в пласмальк

PLOT 8 a. AMD 7, BLOCK IN, OF DICEAN BEACH ADDITION MO 2, ADCORDING TO THE PLAT THEREOF, AS RECORDED PLAT BOOK 2, PAGE SE OF THE PUBLIC OF HAMB - DADE COUNTY - FLORIDA

ALL THAT TRACT OR PARCEL OF LAND CONTAINING HIS ACRESMORE OR LESS SITUATED, LYING AND SEINGLOTS 55 AND TIM BLOCK IS, OF OCEAN BEACH ADDITION W.J. ACCORDING TO THE PLAT THEIR OF RECORDED IN PLAT BOXOC PAGES OF THE PUBLIC RECORDS OF MIAMIDIAGE COUNTY, FLORIDA, AND SEING MORE PARTICULALITY DESCRIPTION FOR THE PROPERTY OF THE PARTICULALITY OF THE PROPERTY AND SEING MORE PARTICULALITY.

BEOM AT A POSITIO CONFEDATITIES INTERSECTION OF THE MORTH PROFF OF WAY MARKING OF STITLED THE WITCH THE PROFESSION OF GERMANDIANCE OF STORY SELECT THE TIME FOR THE TRUE FOR THE PROFESSION OF THE PROFESSION OF A STREET TO A POSITION OF THE PROFESSION OF A STREET TO A POSITION OF THE PROFF OF

LAND CONTAINS 195,000 SE. AND BASACRES

PROJECT RENDERING




PROPOSED NEW ELEVATOR ON NORTH COURTYARD


LOCATION MAP




KEY PLAN



NEW GLASS ELEVATOR ON COURTYARD NE CORNER - JUSTIFICATION



THE VILLA - PROPOSED ELEVATOR FLOOR PLANS



THE VILLA – PROPOSED ELEVATOR SECTION + DETAILS





STUDY OF CASA CASUARINA THE VILLA VERSACE FOR: ALTERNATE LOCATION FOR ELEVATOR

1.- HALLWAYS - NOT POSSIBLE

Width is 3'-9" or 4'-10".

A minimum elevator requires hoist way + walls, existing width are 3'-9" to 4'-10" also, this would block the corridors on 2nd and 3rd floors.

2.- INSIDE ROOMS/SPACES— NOT POSSIBLE IN OFFICE AREA

The required space for the elevator on the 1st Floor would block the access to the actual office area.

On the 2nd Floor would break the elaborate VERSACE finishes on flooring, walls and ceilings,
would also limit the access and the layout of the existing hotel Suite.

On the 3rd Floor there is a walk-in closet all finished in elaborated VERSACE millwork.


IN ANY OTHER INTERIOR AREA/ROOMS

There will be a lot of structural work that would remove a lot of the elaborated finishes on the Villa, most of the suites/rooms have symmetrical layout designs that would be affected.

3.- COURTYARD WEST SIDE:


Although the original location of a previous elevator, this location is going to be visible from the entrance of the Villa and would block the view of the Bell.

THE VILLA - JUSTIFICATION




THE VILLA – 1ST FLOOR







THE VILLA – 2ndFLOOR




THE VILLA – 3rd FLOOR



MINIMUM ACCESIBLE CABIN



THE VILLA – ALTERNATE ELEVATOR INSIDE A SPACE



THE VILLA - PROPOSED ELEVATOR ON COURTYARD EAST SIDE