



APPROVAL HISTORY

Ordinance No. 2020-4383 approved December 9, 2020

Amended Code Sec. 118-395(b)(3) allowing the reconstruction of original interior floor plates even if the underlying lot is non-conforming as to FAR, subject to certain criteria.

PB20-0416 approved March 23, 2021

Conditional Use Permit for a Neighborhood Impact Establishment that included the renovation of the historic structure and existing commercial uses, as well as the introduction of office use

HPB20-0444 approved May 11, 2021

Conditional Use Permit for a Neighborhood Impact Establishment that included the renovation of the historic structure and existing commercial uses, as well as the introduction of office use

PROPOSED MODIFICATIONS

#4: GROUND FLOOR SOUTHWEST CORNER, New awnings

#6: COLLINS AVENUE FRONTAGE. Addition of hedge.

#8: HISTORIC LOBBY, Addition of bar.

#1: 3RD FLOOR FAST FACADE, Removal of eyebrow and replacement of windows to doors.


#5: FIRE EGRESS STAIR. Addition of exterior fire stair from upper roof to lower roof.


#9: 3RD LEVEL EAST FAÇADE. Addition of glass block.

#2: 1996 OCTAGONAL TOWER MODIFICATION. Raise tower 3' in height.


#3: UPPER ROOF RAILING HEIGHT MODIFICATION. Add one course of CMU blocks and cable rail.


#7:SOUTH FACADE OF BANCROFT ROOF MODIFICATIONS. Proposed openings.







1. 3RD FLOOR EAST FACADE. Remove eyebrow and replace windows to doors.























ISOMETRIC VIEW OF PROPOSED CONDITIONS FACING NW AT TERRACE AND STAIR


PHOTOS OF LEVEL 3 TERRACE EXISTING CONDITIONS

2. 1996 OCTAGONAL TOWER MODIFICATION. Raise tower 3' in height.












3. UPPER ROOF RAILING HEIGHT MODIFICATION.


Add one course of CMU blocks and cable rail.







4. GROUND FLOOR SOUTHWEST CORNER. New awnings.














5. FIRE EGRESS STAIR. Addition of exterior fire stair from upper roof to lower roof.






6. COLLINS AVENUE FRONTAGE. Addition of hedge.







7. SOUTH FACADE OF BANCROFT ROOF MODIFICATIONS. Proposed openings.









PHOTO OF EXISTING FACADE PORTION




8. HISTORIC LOBBY. Addition of bar.



























3. CORNER VIEW TOWARDS THE MAIN BAR





BAR EQUIPMENT- POTENTIAL LOCATIONS OF SANIFLOW SYSTEM TO AVOID PENETRATING EXISTING FLOOR








PROPOSED PLUMBING EQUIPMENT TO AVOID PENETRATING EXISTING FLOOR TO BE USED AT BAR

















ELEVATION FACING EAST AT CHEF'S TABLE

SCALE: 3/8" = 1'-0"


REPUBLICATION
PREPARTICAL
PROPERTY CAST

OF THE CAST

OF


ELEVATION FACING NORTH AT CHEF'S COUNTER

SCALE: 3/8" = 1'-0"



ELEVATION FACING WEST AT CHEF'S COUNTER


SCALE: 3/8" = 150"



(4) ELEVATION FACING SOUTH AT CHEF'S COUNTER

SCALE: 3/8" = 1'-0

9. 3RD LEVEL EAST FAÇADE.
ADDITION OF GLASS BLOCK.






VIEWS OF AREA TO REMOVE AT LEVEL 3 TO BE REMOVED



VIEW OF AREA TO REMOVE AT LEVEL 3 TO BE REMOVED



REFERENCE VIEW OF EXISTING GLASS BLOCK AT GROUND LEVEL (TO REMAIN)



DEMOLITION ELEVATION OF PROPOSED GLASS BLOCK WALL AT LEVEL 3



