

PROJECT NAME: Madeleine Village Apartments Rehabilitation

A/E CONSULTANT: KCI Technologies

CONTRACTOR: Florida Construction & Engineering

RPR/CEI:

 Contingency Draw
 No. 1
 DATE CREATED:
 08.09.2021

 DUE DATE:
 08.14.2021

#### **Reason for Contingency Draw:**

This contingency request will reimburse the contractor for the cost of repairing cut and spliced wires discovered inside the kitchen walls along the length of the kitchen counters. Contract documents and architectural plans anticipated that the electrical wiring had been completed safely and to code. The unsafe and unworkmanlike way the electrical wiring was installed remained hidden until the walls were cut to install new plumbing lines for the washer/dryer units. These wires provide service to the countertop receptacles. New lines will be run to the outlets from the panel to correct the condition and bring the wiring to current code requirements.

### **Additional Scope:**

Please submit a proposal itemizing labor/material cost and time proposal for changes in the contract time for the following proposed work:

- 1. Removal of damaged Romex wire in the kitchen at each unit, to be replaced with new 12/2 Romex,
- 2. Install one new GFCI receptable and one new load-controlled receptacle along the countertop,
- 3. Install one AFCI 20 amp. breaker at each unit for modified circuit,
- 4. Removal of the 2 existing junction boxes and relocation,
- 5. Hand dig trench and relocate the conduit,
- 6. Install 2 new junction boxes above doorway,
- 7. Extend wiring between junction boxes, complete wire terminations with Polaris lugs and grounding bushings, data box to remain as is.

### **Contractor's Proposal:**

Please submit the costs for this work which will be included as part of the Contingency. Attach file if more space is needed.

Please refer to the attached.

Amount: \$20,800.00

### **Contingency Summary:**

 $\begin{array}{lll} \mbox{Total Project Contingency:} & $$55,426.00 \\ \mbox{Previous Contingency Draws:} & $$90.00 \\ \mbox{This Contingency Draw:} & $$20,800.00 \\ \mbox{Contingency Balance prior to this change:} & $$55,426.00 \\ \end{array}$ 

Contingency Balance after this change: \$34,626.00

This is not an authorization to proceed with work involving additional costs and/or time. Notification must be given in accordance with the contract documents if any response causes any changes to the contract.

Contractor:	Recommended by Engineer of Record:	Recommended by Architect of Record:
Florida Construction & Engineering	KCI Technologies	The Tamara Peacock Company
Johnny Pay /	Robert Zuccarousigned by:	Cristin Peacock Signed by:
Signed: Johnny Vao	Signed: Robert Euclaro	Signed: (ristin franck
Date: 8/9/2021 5:50 PM PDT	Date: 8/10/2020 1AF9:03 AM EDT	Date: 8/10/92/02/13C41D1:15 PM EDT
Approved by CDBG Projects Coordinator:	Approved by HOME/SHIP Projects Coordinator:	Approved Controller Housing:
Cristina Cabrera	Marcela Rubio	Alice Waters
Signed:	Signed: Marula Kubio	Signed: Muce Waters
Date: 8/10/2021 <sup>E0</sup> 4 <sup>CE</sup> 2:58 PM EDT	Date: 8/10/20216F3#703:01 PM EDT	Date: 8/105/205210604094:46 PM EDT
	Approved by Sr. Capital Project Coordinator:	Approved by Interim Director Housing:
	Pablo Gomez	Alba Taire
	Signed: Pablo Gomes	Signed: Alba Tarre
	Date: 8/9/2021 <sup>D0044</sup> :51 PM EDT	Date: 8/10/2029 <sup>C9</sup> <sup>A45</sup> 4:48 PM EDT



# **Change Order Request No. 4**

TO: City of Miami Beach

Attn: Pablo Gomez / PM

PROJECT: ITB 2020-069-JC
Madeleine Village Building Renovations & Site
Improvements

Date	C.O #
7/28/21	4

Conduit Junction Box Relocation - ASAS

Item	Description	QTY.	UNIT	Unit Price		Total
	This proposal includes: removal of the 2 existing junction boxes and relocation, Hand dig trench and relocate the conduit, Install 2 new junction boxes above doorway, extend wiring between junction boxes, complete wire terminations with polaris lugs and grounding bushings, data box to remain as is for it does not enter into conflict with the new doorway.	1	Item	\$ 8,807.50	\$	8,807.50
				Subtotal	\$	8,807.50
				TOTAL	<i>\$</i>	8,807.50

TOTAL OF PROPOSED CHANGE REQUEST (ADD) \$8,807.50 TOTAL OF PROPOSED CHANGE TIME REQUEST (ADD) 48 Calendar Day Florida Construction & Engineering Inc. Johnny Dao President 7/28/2021 Contractor Name Title Signature Date Having received the above, I hereby certify that the best of my knowledge and belief the same reflects adequate values and that the Contractor is entitled to payment as noted above. City of Coral Gables Pablo Gomez Project Manager Signature Owner Name Title Date

– DS 10 ∕



# **Change Order Request No. 4**

TO: City of Miami Beach

Attn: Pablo Gomez / PM

PROJECT: ITB 2020-069-JC

Madeleine Village Building Renovations & Site
Improvements

Date	C.O #	
7/28/21	5	

Countertop Wiring and Receptacle Repairs - RFI #18

Item	Description	QTY.	UNIT	Unit Price	Total
1	This proposal includes: the removal of damaged Romex wire in the kitchen at every unit, replace with new 12/2 Romex, Intall one new GFCI receptable and one new load controlled receptacle along countertop, Install one AFCI 20 amp breaker at each unit for modified circuit, Existing remaining kitchen receptacles to remain as is, with no modifications. Existig receptacles to remain as is.	1	Item	\$ 11,992.50	\$ 11,992.50
				Subtotal	\$ 11,992.50
F	·			TOTAL	\$ 11,992.50

TOTAL OF PROPOSED CHANGE REQUEST (ADD) \$11,992.50 TOTAL OF PROPOSED CHANGE TIME REQUEST (ADD) 48 Calendar Day Florida Construction & Engineering Inc. Johnny Dao President 7/28/2021 Contractor Name Title Signature Date Having received the above, I hereby certify that the best of my knowledge and belief the same reflects adequate values and that the Contractor is entitled to payment as noted above. City of Coral Gables Pablo Gomez Project Manager Owner Name Title Signature Date

P6

## Madeleine Rehab 6/23/2021



The sanitary line runs to the front of the building and disappears behind the planter. This line will be removed and capped off within the planter.

The distance between the electrical boxes is 9'3"

Please note the water line along the bottom must continue left to feed the hose bib.

Please note electrical enters the building over the right side of the window.



## Madeleine Rehab 6/23/2021



The electrical outlets, water lines & vents are abandoned after the removal of the washer dryer. Note the tankless water heater and disconnect are also abandoned.



7861 Unit 8



#### Florida Construction & Engineering, Inc.

301 Almeria Ave. Suite 360 Coral Gables, Florida 33134 P: (305) 883-7601 Project: Madeleine Village Miami Beach 7861-7871 Crespi Boulevard Miami Beach. Florida 33141

Printed On: Jul 28, 2021 04:23 PM EDT

Engineering, Inc.)

## RFI #18: Kitchen Wires

Status Open

To Pablo Gomez (City of Miami Beach) From Ricardo Esclusa (Florida Construction &

Robert Zuccaro (KCI Technologies Inc.)

Cristin Peacock (The Tamara Peacock Comapny)

**Due Date** Jul 29, 2021

Location Project Stage Course of Construction

Cost Impact Schedule Impact

Spec Section Cost Code

Drawing Number Reference

**Linked Drawings** 

**Date Initiated** 

Received From Jordan De Armas (All Star Electric)

Jul 26, 2021

Copies To Johnny Dao (Florida Construction & Engineering, Inc.), Ricardo Esclusa (Florida Construction & Engineering, Inc.), Isabel

Fernandez (Florida Construction & Engineering, Inc.), Sebastian Fraiese (Florida Construction & Engineering, Inc.), Jonathan Geiger (KCI Technologies Inc.), Pablo Gomez (City of Miami Beach), Melanie Melanie (The Tamara Peacock Comapny)

### **Activity**

#### Question

#### Question from Ricardo Esclusa Florida Construction & Engineering, Inc. on Monday, Jul 26, 2021 at 02:43 PM EDT

Upon site visit on Friday, we discovered some cut and spliced wires inside the kitchen walls. It appears to service the counter top receptacles. This would need to be corrected before any inspections can be performed. This is an unforeseen condition that was discovered after the plumbers opened the wall to run their lines. It seems to be the case at every unit. Please advise accordingly.

#### Attachments

Madeline Village Kitchen Wires 2.jpg, Madeline Village Kitchen Wires 1.jpg

#### Awaiting an Official Response

Listin Duwch

The spliced wires in the kitchen is a code violation and will need to be corrected to be code compliant. New lines will need to be run to the outlets from the panel to correct the condition.

7/29/2021





