| Owner CARSON BRADFORD, JR       | Mailing Address               | Permit No. 14743          | Cost \$ 9,000.      |  |
|---------------------------------|-------------------------------|---------------------------|---------------------|--|
| Lot 4 Block 15                  | Subdivision Nautilus          | Address 4635 Alton Re     | oad.                |  |
| General Contractor Garson Br    | adford, jr.   3304            | Bond No. 2626             |                     |  |
| Architect Robert M. Little      |                               | Engineer                  | To I hay the        |  |
| Zoning Regulations: Use RD      | Area 17                       | Lot Size 65 % 103         |                     |  |
| Building Size: Front 5          | 3 <sup>1</sup> 1 Depth 50     | Height 14 Sto             | ries <sup>One</sup> |  |
| Certificate of Occupancy No.    |                               | Use Residence- 6 rooms &  | attached garage     |  |
| Type of Construction c-b-       | s Foundation Spread           | footing Roof Tile         | Date Oct. 4-1940    |  |
| Plumbing Contractor Super F     | Plumbing Co. # 14238          | Sewer Connection 1        | Date Oct. 5-1940    |  |
|                                 |                               | Temporary Closet 1        | ,                   |  |
| Plumbing Contractor             | Laundry tub                   |                           | Date                |  |
| Water Closets 2                 | Bath Tubs 1                   | Floor Drains              |                     |  |
| Lavatories 2                    | Showers 1                     | Grease Traps              |                     |  |
| Urinals                         | Sinks 1                       | Drinking Fountains        |                     |  |
| Gas Stoves 1                    | Gas Heaters 1                 | Rough Approved            | Date                |  |
| Gas Radiators                   | Gas Turn On Approved          | Bell - 10/9/40            |                     |  |
| Septic Tank Contractor          |                               | Tank Size                 | Date                |  |
| Oil Burner Contractor           |                               | Tank Size                 | Date                |  |
| Sprinkler System                |                               |                           |                     |  |
| Electrical Contractor Triangle  | Electric Co,#15982            | Address                   | Date 007.24-40      |  |
| Switch <sub>17</sub>            | Range Motors                  | Fans Temporary Service    |                     |  |
| OUTLETS Light 16 Receptacles 22 | HEATERS Water 1<br>Space      | Centers of Distribution 2 |                     |  |
| Radio: 1                        | Refrigerators 1               |                           |                     |  |
| =                               | Irons 1                       | Sign Outlets              |                     |  |
| No. FIXTURES 16                 | Electrical Contractor         |                           | Date                |  |
| FINAL APPROVED BY Linco         | In Brown, tr. Date of Service | November 21, 1940         |                     |  |

Alterations or Repairs—Over # 26648 Painting-inside & outside- Ardis McCully Painting- \$400 Feb. 4, 1948

## **ALTERATIONS & ADDITIONS**

Building Permits: #42688 Painting: Martell Painting Co:

\$450: Sept 16, 1953

#63569 Florida Roofing Co: Repairs to roof - \$138.00 - Nov. 10, 1960 #14847-Sego Industries-Replace7 jalousies with 7 alum awning ones-\$500-4-2-79 #15911-Youngblood Roofing-Re-roof 27 sqs-\$5565-11-1-79

Plumbing Permits:

Electrical Permits# 36989 Astor Electric Service: 1 motor - July 11, 1952 - HOR 10-6-52 #52548 Astor Elec: 1 Motor (1HP) - Aug. 22, 1958

## COASTAL CONTROL ZONE

## CUMULATIVE COST OF CONSTRUCTION OF PERMITS ISSUED

| DATE   | PROCESS | DESCRIPTION | WORK | CUMULATIVE | APPRAISED BLDG.      |     |          | BUILDING  |
|--------|---------|-------------|------|------------|----------------------|-----|----------|-----------|
| ISSUED | NO.     | OF WORK     | COST | WORK COST  | VALUE BEFORE REMODEL | 0/0 | COMMENTS | PERMIT NO |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            | ,                    |     |          |           |
|        |         | •           |      |            |                      |     |          | ·         |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         | 1           |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
| -      |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             | İ    |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        |         |             |      | ,          |                      |     |          |           |
|        |         |             |      |            |                      |     |          |           |
|        | ·       |             |      |            |                      |     |          |           |