


EXISTING SITE PLAN



EXISTING CHALLENGES



LOOSE CONCRETE PAVERS



INAPPROPRIATE LANDSCAPING




ACCESSIBILITY ISSUES



AGED PAVING



UNSAFE WIRING



OUTDATED STREET LAMPS



BROKEN LIGHT FIXTURES



FADED CROSSWALK BRANDING

KEY DIRECTIONAL PLAN FOR CONTEXT PHOTOS



CONTEXT PHOTO



PHOTO 01



PHOTO 02



PHOTO 03



PHOTO 04




PHOTO 05



PHOTO 06



PHOTO 07



PHOTO 08



PHOTO 09



PHOTO 10



PHOTO 11



PHOTO 12



PHOTO 13



PHOTO 14



PHOTO 15



PHOTO 16



PHOTO 17



PHOTO 18



PHOTO 19



PHOTO 20




PHOTO 21



PHOTO 22



PHOTO 23



PHOTO 24



PHOTO 25



PHOTO 26



PHOTO 27



PHOTO 28



PHOTO 29



PHOTO 30



PHOTO 31



PHOTO 32



PHOTO 33



PHOTO 34



PHOTO 35



PHOTO 36



PHOTO 37



PHOTO 38



PHOTO 39



PHOTO 40



PHOTO 41



PHOTO 42



PHOTO 43



PHOTO 44



PHOTO 45



PHOTO 46



PHOTO 47



PHOTO 48



PHOTO 49



PHOTO 50



PHOTO 51



PHOTO 52



PHOTO 53



PHOTO 54



PHOTO 55



PHOTO 56



PHOTO 57



PHOTO 58



PHOTO 59



PHOTO 60



PHOTO 61



PHOTO 62



PHOTO 63



PHOTO 64



PHOTO 65



PHOTO 66




PHOTO 67



PHOTO 68



PHOTO 69



PHOTO 70



PHOTO 71



PHOTO 72



PHOTO 73



PHOTO 74



PHOTO 75



PHOTO 76



PHOTO 77



PHOTO 78



PHOTO 79



PHOTO 80



PHOTO 81



PHOTO 82



PHOTO 83



PHOTO 84