



Partial roof plan showing the eight-sided copper cupula. (8)



1939 photograph of the newly completed renovations to 947 Lincoln Road including the addition of a corner roof-top eight-sided copper cupula. (9)



1962 photographs of 947 Lincoln Road - corner and Michigan Avenue elevations courtesy of the Miami Dade Property Appraiser Office. By this time the cupula had already be removed. (10)



OCT • 62



JUN • 63

1963 photographs of 947 Lincoln Road are courtesy of the Miami Dade Property Appraiser Office. (10)

Above Photo: North and rear (Lincoln Lane) elevation with partial east elevation at left.

Below Photo: North (Lincoln Lane) elevation at left and Michigan Avenue elevation at right.





IN THESE AERIAL PHOTOGRAPHS COURTESY OF THE CITY OF MIAMI BEACH PUBLIC WORKS DEPARTMENT - THE EIGHT-SIDEED CUPULA CAN BE CLEARLY SEEN IN THE 1941 AND 1954 PHOTOGRAPHS. HOWEVER IT HAD BEEN REMOVED BY THE TIME OF THE 1959 PHOTO.

EXTERIOR 2017 PHOTOGRAPHS



ABOVE: 2017 PHOTOGRAPH WITH SOUTH ELEVATION on LINCOLN ROAD AT RIGHT AND THE WEST ELEVATION (MICHIGAN AVENUE) AT RIGHT.

BELOW: 2017 PHOTOGRAPH SHOWS CORNER ENTRANCE WITH DIXON DESIGNED CLADDING WHICH ENDS NOT FAR ONTO MICHIGAN AVENUE





LEFT PHOTO: TWO STORY SECTION AT NORTHERN SIDE OF PROPERTY

PHOTO BELOW: PARTIAL WEST ELEVATION FACING MICHIGAN AVENUE

